

TENNESSEE VALLEY AUTHORITY

5N 157B Lookout Place

April 14, 1986

86 APR 21 9:59

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Dr. J. Nelson Grace, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - SUPPLEMENTAL RESPONSE TO VIOLATIONS  
390/85-63-03, 391/85-52-01 - FAILURE TO ESTABLISH AN ADEQUATE WELDING  
INSPECTION PROCEDURE

This is our supplemental response to R. D. Walker's letter dated January 17, 1986, report Nos. 50-390/85-63, 50-391/85-52, citing activities at the Watts Bar Nuclear Plant which appeared to be in violation of NRC regulations. Our initial response was submitted on February 21, 1986.

As discussed with Bob Carroll on April 1, 1986, the date of April 1, 1986 for completion of the corrective actions indicated in our final report was not met. The procedure WBN-QCI-4.03 has been revised; however, the review and approval cycle took longer than anticipated. The training to the revised procedure will be complete by April 16, 1986.

If you have any questions, please get in touch with R. H. Shell at  
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
R. L. Gridley  
Manager of Licensing

cc: Mr. James Taylor, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8605120401 860414  
PDR ADOCK 05000390  
Q PDR