

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

REGION II
ATLANTA, GEORGIA

May 6, 1983 ⁸³ MAY 10 2:19

WBRD-50-390/81-27
WBRD-50-391/81-26
WBRD-50-390/81-70
WBRD-50-391/81-66

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - INSUFFICIENT DOCUMENTATION FOR PROTECTIVE DEVICES - WBRD-50-390/81-27, WBRD-50-391/81-26, WBRD-50-390/81-70, WBRD-50-391/81-66- SUPPLEMENTAL INFORMATION

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on March 13, 1981 in accordance with 10 CFR 50.55(e) as NCR 3001R R1. Interim reports were submitted on April 10, May 21, July 9, and August 6, 1981 and July 30, 1982. As specified in my letter to you dated September 24, 1981, a related nonconformance, NCR 3523R, would be handled in conjunction with NCR 3001R R1. Our final report on both NCRs was submitted on January 6, 1983. Supplemental information was provided on March 31, 1983.

As discussed with NRC-OIE Inspector L. Watson on May 2, 1983, the date of April 30, 1983 for completion of the unit 1 corrective actions, as indicated in our previous submittal, was not met.

One Field Change Request, which was initiated to clarify drawing notes, remains to be closed. All field modifications and reinspections for the unit 1 protective devices have been completed. We now anticipate completing the unit 1 corrective actions by May 31, 1983.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

OFFICIAL COPY

IE 27