

NRC TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

83 APR 13 AID : 32

April 11, 1983

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - NRC-OIE REGION II INSPECTION REPORT
50-390/82-20 AND 50-391/82-20 - SECOND SUPPLEMENTAL RESPONSE TO DEVIATIONS
390,391/82-20-01

The subject inspection report cited TVA with four deviations. Our responses were submitted December 16, 1982. A supplemental response was submitted on January 31, 1983. In that supplemental response TVA committed to complete the corrective actions as specified for the subject deviation by March 31, 1983.

As discussed with NRC-OIE Inspector P. Fredrickson on March 30-31, 1983, the date of March 31, 1983 for completion of the corrective actions was not met. Reinspection identified two dampers which did not bear the mark number as depicted on their applicable drawings. However, it was determined that these dampers provide adequate protection; thus the drawings will be revised to reflect the mark numbers of the dampers as-installed. Also, one additional damper requiring replacement has been found (in addition to the three mentioned in our previous submittal). The corrective actions on this matter will be completed by April 30, 1983.

If you have any questions, please get in touch with R. H. Shell at
FTS 858-2688.

To the best of my knowledge, I declare the statements contained herein to be complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339