

TENNESSEE VALLEY AUTHORITY NRC REGION II  
CHATTANOOGA, TENNESSEE 37401 ATLANTA, GEORGIA  
400 Chestnut Street Tower II

81 OCT 26 AIO: 2

October 22, 1981

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - NRC-OIE INSPECTION REPORT  
50-390/80-36, 50-391/80-28

The subject inspection report dated March 10, 1981 cited TVA with three violations. Responses to the violations were submitted on April 6, 1981. In the response to violation 390/81-36-03, 391/81-28-03, TVA committed to replace 1/2-inch diameter carbon steel piping with stainless steel piping by May 31, 1981. This piping supplies prelube and motor cooling water to the ERCW pumps. As discussed with Inspector D. Quick on October 1, 1981, this work will now be completed before fuel loading of unit one.

If you have any questions, please get in touch with R. H. Shell at  
FTS 857-2581.

To the best of my knowledge, I declare the statements contained herein are  
complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
L. M. Mills, Manager

Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555