TENNESSEE VALLEY AUTHORITY

CHATTANOOGA TENNESSEE 37401 400 Chestnut Street Tower II

8 | DEC 21 ADScember 16, 1981

WBRD-50-390/81-48

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNIT 1 - ERCW SEISMIC SUPPORT DEFICIENCY - WBRD-50-390/81-48 - FOURTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on May 6, 1981 in accordance with 10 CFR 50.55(e) as NCR WBN SWP 8127. Interim reports were submitted on June 5, September 15, and October 28, 1981. TVA is still investigating this nonconformance and expects to provide additional information by February 16, 1982. TVA considers 10 CFR Part 21 applicable to this deficiency.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mille, Manager

Nuclear Regulation and Safety

cc: Mr. Richard C. DeYoung, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

IE27

8112240255 811216 PDR ADOCK 05000390 S PDR