RC FORM 591M PART 1 -2003) CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION T AND COMPLIANCE INSPECTION
LICENSEE/LOCATION Hotwell Services, In 5708 Rickshaw Ln. Plano, Texas 75094	C.	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415
DOCKET NUMBER(S)	4. LICENSE NUMBER	F(S) 5. DATE(S) OF INSPECTION June 17, - Aug 27, 2018
030-37612	42-31298-01	० सम् १ । । । । ।
1. Based on the 2. Previous viola 3. The violation(identified, non-renue) Nure G-1600, to	inspection findings, no violations were identi- ation(s) closed. s), specifically described to you by the inspective, and corrective action was or is being a exercise discretion, were satisfied. ed Violation(s) was/were discussed involving	onditions of your license. The inspection consisted of selective examinations and observations by the inspector. The inspection findings are as follows: iffied. In the inspe
	Licenses's Statement of C	orrective Actions for Item 4, above.
I hereby state that, withi corrective actions is ma date when full complian Title	n 30 days, the actions described by me to the	e inspector will be taken to correct the violations identified. This statement of 0 CFR 2.201 (corrective steps already taken, corrective steps which will be taken ther written response to NRC will be required, unless specifically requested. Signature Date
LICENSEE'S REPRESENTATIVE		m. // / 08/27/09

SUNSI Review Completed By: /RA/

Michael Reichard

X Public

Non-Sensitive