



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

September 12, 2008

MEMORANDUM TO: Michele L. Burgess, Health Physicist (MS-8F5)
Medical Safety & Events Assessment Branch
Division of Materials Safety & State Agreements

FROM: Michael Vasquez, Acting Chief */RA/*
Nuclear Materials Safety Branch-A
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for September 2008. In addition, enclosed are the licensee event report evaluation forms for the events closed in July and August 2008, detailing Region IV's response to these events.

Enclosures:

1. September 2008 RIV DNMS Licensee Event Reports Summary Table
2. LER evaluation forms for RIV events closed in July and August 2008

cc w/enclosures (Report):

EECollins
AHowell
CLCain
VHCampbell
GMVasquez
JEWhitten
DBSpitzberg
JLThompson
LER File

SUNSI review completed: ADAMS: Yes Initials: JLT

Publicly Available Non-Sensitive

DOCUMENT NAME: s:\dnms!\nmib\LERs\2008\08 & 09-2008.doc

RIV:DNMS:NMSB-A	AC:NMSB-A
JLThompson	GMVasquez
/RA/	/RA/
09/12/2008	09/13/2008

OFFICIAL RECORD COPY T=Telephone E=E-mail F=Fax

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - SEPTEMBER 2008

ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
ML080940575	2/29/08	2/29/08	SABIA Corporation	11-27727-01	10 CFR 2202 & 10 CFR 30.50	Leaking source and unplanned contamination of worker	Katanic	Open
44281	6/9/08	6/10/08	Department of Commerce NIST	05-03166-05	10 CFR 30.50	Plutonium contamination event involving contaminated personnel and buildings	Thompson	Open
ML081760323	5/21/08	6/17/08	FMRI	SMB-911	10 CFR 50.72	Concentration of radioactive materials exceeding limits in 10 CFR 20.2203	Evans	Open
44371	7/18/08	7/28/08	Memorial Hospital Sheridan	49-10982-02	10 CFR 35.3045	Medical event involving wrong isotope used in patient treatment	Thompson	Open
ML082001222	6/23/08	7/18/08	Kakivik Asset Management	50-27667-01	10 CFR 30.50	Report of a radiography source disconnect	Donovan	Open
ML082001077	4/25/08	4/25/08	Construction Engineering Labs	53-23293-01	10 CFR 20.1802	Loss of a portable nuclear gauge which was subsequently recovered	Munoz	Open
ML082530557	6/4/08	9/5/08	USAF Wilford Hall Medical Center	42-23539-01AF	10 CFR 35.3047	Patient with undetected pregnancy received therapeutic dose of iodine- 131	Donovan	Open

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - SEPTEMBER 2008

ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
ML082040079	6/23/08	7/18/08	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
ML081640401	4/23/08	5/7/08	General Electric	DPR-1	License Condition	Hot slag contacted licensed material while cutting steel shielding in BWR	Evans	Closed (report attached)
ML081790616	5/30/08	6/18/08	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
ML081790657	6/07/08	6/26/08	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
ML081790076	5/25/08	6/23/08	Baker Hughes	17-27437-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
ML082000193	5/22/08	7/8/08	Baker Hughes	17-27437-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
ML081280478	4/5/08	5/7/08	Rancho Seco	DPR-54	10 CFR 50.72	Debris fire occurred in reactor building	Garcia	Closed (report attached)
ML081220823	5/1/08	5/1/08	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Opened in error, subsequently closed as ML082040079 above
ML082200411	7/2/08	8/5/08	Baker Hughes	17-27437-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)