



UNITED STATES  
REGION III  
2443 WARRENVILLE ROAD, SUITE 210  
LISLE, ILLINOIS 60532-4352

Donald Peck, Ph.D.  
Radiation Safety Officer  
Henry Ford Hospital  
2799 West Grand Blvd.  
Detroit, MI 48202

SEP 26 2008

Dear Dr. Peck:

Enclosed is Amendment No. 71 to your NRC Material License No. 21-04109-16 in accordance with your request. Please note that the changes made to your license are printed in **bold** font.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers. If you have any questions concerning this amendment please contact me at either (630) 829-9841 or (800) 522-3025.

Please note that the changes made to your license are printed in **bold** font.

**I noted that your recent letters to us dated April 16, 2008, and September 25, 2008, listed our former address, "801 Warrenville Road, Lisle, IL 60532-4351."**

**Please note, for future reference and correspondence, our address changed in April 2004 to "2443 Warrenville Road, Suite 210, Lisle, IL 60532-4352."**

**Also, your letter to us dated September 25, 2008, contained errors, in that the license number given was wrong. You requested a change to license no. "21-04108-16" instead of "21-04109-16." You also stated your docket no. was "030-02403" but it really is "030-02043." We assumed these were typos and adjusted this license.**

**Please note that by License Condition No. 24, which has been updated with this amendment, you are required to comply with the requirements of the "Order Imposing Increased Controls" (ADAMS Accession No. (ML0053130218) published in the Federal Register on December 1, 2005 (70 FR 72128); and with the "Order Imposing Fingerprinting and Criminal History Records Check Requirements for Unescorted Access to Certain Radioactive Materials" (Fingerprinting Order) (ADAMS Accession No. (ML073230831) published in the Federal Register on December 13, 2007 (72 FR 70901).**

**This License Condition requires that you complete implementation of said requirements by the first day that radionuclides in quantities of concern are**

D. Peck

possessed at or above the limits specified in "Table 1: Radionuclides of Concern" contained within the Fingerprinting Order, and notify, in writing, the Director, Office of Federal and State Materials and Environmental Management Programs, U.S. NRC, Washington, DC, 20555, when you have completed the requirements of this License Condition.

Our records indicate that you provided responses to the NRC dated December 7, 2005, and March 4, 2008, and that you are currently implementing the Increased Controls requirements. Your future responses must be marked as "Security-Related Information - Withhold from Public Disclosure under 10 CFR 2.390." Please note that these response documents are now included in the last Condition of your license, No. 25.

The *Implementing Guidance for Licensees that Possess Radioactive Material Quantities of Concern and Q&A's* (ML053130233) and *Supplemental Q&A's to the Implementing Guidance and IC's* are located on the NRC website at the following links:

<http://www.nrc.gov/reading-rm/doc-collections/enforcement/security/2005/ml053130233.pdf>

<http://www.nrc.gov/reading-rm/doc-collections/enforcement/security/2007/ml0622901021-01-24-07.pdf>

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers.

NRC's Regulatory Issue Summary (RIS) 2005-31 provides criteria to identify security-related sensitive information and guidance for handling and marking of such documents. This ensures that potentially sensitive information is not made publicly available through ADAMS, the NRC's electronic document system.

Pursuant to NRC's RIS 2005-31 and in accordance with 10 CFR 2.390, this letter and the enclosed license document are exempt from public disclosure because their disclosure to unauthorized individuals could present a security vulnerability.


The RIS may be located on the NRC Web site at: <http://www.nrc.gov/reading-rm/doc-collections/gen-comm/reg-issues/2005/ri200531.pdf> and the link for frequently asked questions regarding protection of security related sensitive information may be located at: <http://www.nrc.gov/reading-rm/sensitive-info/faq.html>.

You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you. This could include issuance of a notice of

D. Peck

violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions. Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.

Sincerely,



Colleen Carol Casey  
Materials Licensing Branch

License No. 21-04109-16  
Docket No. 030-02043

Enclosure:

Amendment No. 71