

US Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

October 3, 2008

Subject: 10CFR Part 21 Reporting
Thread sealant Issue


The enclosed reports address a reportable notification for thread sealant supplied by Namco to TVA – Watts Bar Nuclear Plant, Dominion Nuclear Connecticut, Ameren-Callaway Plant, Alabama Power – Farley Nuclear Plant, New Brunswick – Point Lepreau Gen. Station.

A copy of the report has also been sent to each of the affected users, TVA – Watts Bar Nuclear Plant, Dominion Nuclear Connecticut, Ameren- Callaway Plant, Alabama Power – Farley Nuclear Plant, New Brunswick – Point Lepreau Gen. Station.

On September 19, 2008, Namco determined that it had shipped product that did not meet the customer purchase order requirements. Namco supplied clear thread sealant instead of white thread sealant. The thread sealants are the same except that the white has an additional pigmentation additive. Namco began an evaluation and on September 29, 2008, determined that it did not have the capability to determine the impact to the supplied users. Therefore in accordance with 10CFR Part 21, Namco provided notification.

Namco has reviewed previous purchase orders of thread sealant and determined that these are the only affected customers.

Regards.



Tony King
Vice President/General Manager
2013 W. Meeting Street
Lancaster, SC 29720
Phone: (803) 289 – 1361

TE19
NRA



Namco Information Notice: 2008-01
October 3, 2008

Subject: Namco Order 76058 for Ameren – Callaway Plant

From: *Tony King*

Tony King
Vice President/General Manager
2013 W. Meeting Street
Lancaster, SC 29720
Phone: (803) 289 – 1361

Items Affected By This Information Notice:

Thread sealant provided under Namco order number 76058 (Ameren PO 383106 SR). The thread sealant is identified by Namco part number EH459-20000, lot 411920 (Ameren part number 7649033).

Purpose:

The purpose of this Namco Information Notice is to alert Ameren that as of September 19, 2008, Namco became aware of the possibility of a situation which may impact the performance of your equipment. Namco began an evaluation and determined on September 29, 2008, that it did not have the capability to determine the impact to your organization.

We are informing you of this circumstance in accordance with 21.21 (b) of 10CFR21.

Applicability:

This notice applies only to the thread sealant mentioned above supplied by Namco under Ameren PO 383106 SR. Namco Qualification Test Report (Qtr126) requires white thread sealant and Ameren PO 383106 SR requires material in accordance with Qtr 126.

Discussion:

Namco has determined that the material provided did not meet the requirements of Ameren PO 383106 SR.

Specifically the discrepancies are:

1. Clear thread sealant was provided instead of white thread sealant.

Per statement from Namco engineering, the materials are the same except that the white material has an additional pigmentation additive.

Corrective Action

Namco commercially grade dedicates this material through material testing at a third party. The color check has been added to the material test specifications. All material tests are reviewed by quality personnel as part of the acceptance plan.

Action Required

Contact Namco Customer Service at 1-800-476-6952 to obtain an RMA number for return and replacement of the material.

10CFR21 Implications

Namco requests that the recipient of this notice review it and take appropriate action in accordance with 10CFR21.

If there are any questions or concerns, please contact:

Ken Gould

Quality Manager

Namco Controls

2013 W. Meeting Street

Lancaster, SC 29720

Phone: (803) 289 -1362

Fax: (803) 289 -1367



Namco Information Notice: 2008-01
October 3, 2008

Subject: Namco Order 76054 for Alabama Power – Farley Nuclear Plant

From: *Tony King*

Tony King
Vice President/General Manager
2013 W. Meeting Street
Lancaster, SC 29720
Phone: (803) 289 – 1361

Items Affected By This Information Notice:

Thread sealant provided under Namco order number 76054 (Alabama Power PO QP080620). The thread sealant is identified by Namco part number EC212-10102, lot 411922 (Alabama Power part number 0000000044447F).

Purpose:

The purpose of this Namco Information Notice is to alert Alabama Power that as of September 19, 2008, Namco became aware of the possibility of a situation which may impact the performance of your equipment. Namco began an evaluation and determined on September 29, 2008, that it did not have the capability to determine the impact to your organization.

We are informing you of this circumstance in accordance with 21.21 (b) of 10CFR21.

Applicability:

This notice applies only to the thread sealant mentioned above supplied by Namco under Alabama Power PO QP080620. Namco Qualification Test Report (Qtr142) requires white thread sealant and Alabama Power PO QP080620 requires material in accordance with Qtr 142.

Discussion:

Namco has determined that the material provided did not meet the requirements of Alabama Power PO QP080620.

Specifically the discrepancies are:

1. Clear thread sealant was provided instead of white thread sealant.

Per statement from Namco engineering, the materials are the same except that the white material has an additional pigmentation additive.

Corrective Action

Namco commercially grade dedicates this material through material testing at a third party. The color check has been added to the material test specifications. All material tests are reviewed by quality personnel as part of the acceptance plan.

Action Required

Contact Namco Customer Service at 1-800-476-6952 to obtain an RMA number for return and replacement of the material.

10CFR21 Implications

Namco requests that the recipient of this notice review it and take appropriate action in accordance with 10CFR21.

If there are any questions or concerns, please contact:

Ken Gould

Quality Manager

Namco Controls

2013 W. Meeting Street

Lancaster, SC 29720

Phone: (803) 289 - 1362

Fax: (803) 289-1367



Namco Information Notice: 2008-01
October 3, 2008

Subject: Namco Order 76510 for Dominion – Connecticut

From:

Tony King

Tony King
Vice President/General Manager
2013 W. Meeting Street
Lancaster, SC 29720
Phone: (803) 289 – 1361

Items Affected By This Information Notice:

Thread sealant provided under Namco order number 76510 (Dominion PO 45616361). The thread sealant is identified by Namco part number EH459-20000, lot 412005 (Dominion part number M2940101).

Purpose:

The purpose of this Namco Information Notice is to alert Dominion that as of September 19, 2008, Namco became aware of the possibility of a situation which may impact the performance of your equipment. Namco began an evaluation and determined on September 29, 2008, that it did not have the capability to determine the impact to your organization.

We are informing you of this circumstance in accordance with 21.21 (b) of 10CFR21.

Applicability:

This notice applies only to the thread sealant mentioned above supplied by Namco under Dominion PO 45616361. Namco Qualification Test Report (Qtr126) requires white thread sealant and Dominion PO 45616361 requires material in accordance with Qtr 126.

Discussion:

Namco has determined that the material provided did not meet the requirements of Dominion PO 45616361.

Specifically the discrepancies are:

1. Clear thread sealant was provided instead of white thread sealant.

Per statement from Namco engineering, the materials are the same except that the white material has an additional pigmentation additive.

Corrective Action

Namco commercially grade dedicates this material through material testing at a third party. The color check has been added to the material test specifications. All material tests are reviewed by quality personnel as part of the acceptance plan.

Action Required

Contact Namco Customer Service at 1-800-476-6952 to obtain an RMA number for return and replacement of the material.

10CFR21 Implications

Namco requests that the recipient of this notice review it and take appropriate action in accordance with 10CFR21.

If there are any questions or concerns, please contact:

Ken Gould

Quality Manager

Namco Controls

2013 W. Meeting Street

Lancaster, SC 29720

Phone: (803) 289 - 1362

Fax: (803) 289-1367



Namco Information Notice: 2008-01
October 3, 2008

Subject: Namco Order 75509 for TVA – Watts Bar Nuclear Plant

From:

A handwritten signature in cursive script that reads "Tony King".

Tony King
Vice President/General Manager
2013 W. Meeting Street
Lancaster, SC 29720
Phone: (803) 289 – 1361

Items Affected By This Information Notice:

Thread sealant provided under Namco order number 75509 (TVA PO 00070953). The thread sealant is identified by Namco part number EH459-20000, lot 411838 (TVA part number BVG814N).

Purpose:

The purpose of this Namco Information Notice is to alert TVA that as of September 19, 2008, Namco became aware of the possibility of a situation which may impact the performance of your equipment. Namco began an evaluation and determined on September 29, 2008, that it did not have the capability to determine the impact to your organization.

We are informing you of this circumstance in accordance with 21.21 (b) of 10CFR21.

Applicability:

This notice applies only to the thread sealant mentioned above supplied by Namco under TVA PO 00070953. Namco Qualification Test Report (Qtr126) requires white thread sealant and TVA PO 00070953 requires material in accordance with Qtr 126.

Discussion:

Namco has determined that the material provided did not meet the requirements of TVA PO 00070953.

Specifically the discrepancies are:

1. Clear thread sealant was provided instead of white thread sealant.

Per statement from Namco engineering, the materials are the same except that the white material has an additional pigmentation additive.

Corrective Action

Namco commercially grade dedicates this material through material testing at a third party. The color check has been added to the material test specifications. All material tests are reviewed by quality personnel as part of the acceptance plan.

Action Required

Contact Namco Customer Service at 1-800-476-6952 to obtain an RMA number for return and replacement of the material.

10CFR21 Implications

Namco requests that the recipient of this notice review it and take appropriate action in accordance with 10CFR21.

If there are any questions or concerns, please contact:

Ken Gould

Quality Manager

Namco Controls

2013 W. Meeting Street

Lancaster, SC 29720

Phone: (803) 289 -1362

Fax: (803) 289-1367



Namco Information Notice: 2008-01
October 3, 2008

Subject: Namco Order 74743 for New Brunswick – Point Lepreau

From: *Tony King*

Tony King
Vice President/General Manager
Danaher Controls
2013 W. Meeting Street
Lancaster, SC 29720
Phone: (803) 289 - 1361

Items Affected By This Information Notice:

Thread sealant provided under Namco order number 74743 (New Brunswick PO 4500296643). The thread sealant is identified by Namco part number EC212-10102, lot 411718 (New Brunswick part number 7421796W).

Purpose:

The purpose of this Namco Information Notice is to alert New Brunswick that as of September 19, 2008, Namco became aware of the possibility of a situation which may impact the performance of your equipment. Namco began an evaluation and determined on September 29, 2008, that it did not have the capability to determine the impact to your organization.

We are informing you of this circumstance in accordance with 21.21 (b) of 10CFR21.

Applicability:

This notice applies only to the thread sealant mentioned above supplied by Namco under New Brunswick PO 4500296643. Namco Qualification Test Report (Qtr142) requires white thread sealant and New Brunswick PO 4500296643 requires material in accordance with Qtr 142.

Discussion:

Namco has determined that the material provided did not meet the requirements of New Brunswick PO 4500296643.

Specifically the discrepancies are:

1. Clear thread sealant was provided instead of white thread sealant.

Per statement from Namco engineering, the materials are the same except that the white material has an additional pigmentation additive.

Corrective Action

Namco commercially grade dedicates this material through material testing at a third party. The color check has been added to the material test specifications. All material tests are reviewed by quality personnel as part of the acceptance plan.

Action Required

Contact Namco Customer Service at 1-800-476-6952 to obtain an RMA number for return and replacement of the material.

10CFR21 Implications

Namco requests that the recipient of this notice review it and take appropriate action in accordance with 10CFR21.

If there are any questions or concerns, please contact:

Ken Gould

Quality Manager

Namco Controls

2013 W. Meeting Street

Lancaster, SC 29720

Phone: (803) 289 - 1362

Fax: (803) 289-1367