

## UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D.C. 205555-0001

October 24, 2008

Vice President, Operations Entergy Operations, Inc. River Bend Station 5485 US Highway 61N St. Francisville, LA 70775

SUBJECT: RIVER BEND STATION, UNIT 1 - CLOSEOUT OF GENERIC LETTER 2007-01,

"INACCESSIBLE OR UNDERGROUND POWER CABLE FAILURES THAT

DISABLE ACCIDENT MITIGATION SYSTEMS OR CAUSE PLANT

TRANSIENTS" (TAC NO. MD4371)

## Dear Sir or Madam:

On February 7, 2007, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 2007-01, "Inaccessible or Underground Power Cable Failures That Disable Accident Mitigation Systems or Cause Plant Transients" (Agencywide Documents Access and Management System (ADAMS) Accession No. ML070360665). GL 2007-01 requested that licensees provide the following information within 90 days of the date of the GL:

- (1) A history of inaccessible or underground power cable failures for all cables that are within the scope of Section 50.65 of Title 10 of the *Code of Federal Regulations* (10 CFR 50.65, the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and
- (2) A description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support emergency diesel generators (EDGs), offsite power, emergency service water (ESW), service water, component cooling water, and other systems that are within the scope of 10 CFR 50.65 (the Maintenance Rule).

In your letter dated May 3, 2007 (ADAMS Accession No. ML071280224), you provided the information requested in GL 2007-01 including:

- (1) A history of inaccessible or underground power cable failures for all cables that are within the scope of 10 CFR 50.65 (the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and
- (2) A description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support EDGs, offsite power, ESW, service water, component cooling water, and other systems that are within the scope of 10 CFR 50.65 (the Maintenance Rule).

The NRC staff has reviewed the submitted information and has concluded that, for River Bend Station, Unit 1, your response to GL 2007-01 is adequate. Based on this review, your response to GL 2007-01 is considered closed and no further action is requested of you at this time.

If you have any questions regarding this letter, please contact me at (301) 415-2296.

Sincerely,

Carl F. Lyon, Project Manager Plant Licensing Branch IV

Division of Operating Reactor Licensing Office of Nuclear Reactor Regulation

Docket No. 50-458

cc: See next page

River Bend Station (10/9/2008)

CC:

President of West Feliciana Police Jury P.O. Box 1921 St. Francisville, LA 70775

Mr. Jim Calloway Public Utility Commission of Texas 1701 N. Congress Avenue Austin, TX 78711-3326

Ms. H. Anne Plettinger 3456 Villa Rose Drive Baton Rouge, LA 70806

**Additional Distribution via Listserv** 

3

The NRC staff has reviewed the submitted information and has concluded that, for River Bend Station, Unit 1, your response to GL 2007-01 is adequate. Based on this review, your response to GL 2007-01 is considered closed and no further action is requested of you at this time.

If you have any questions regarding this letter, please contact me at (301) 415-2296.

Sincerely,

/RA by Jack N. Donohew for/

Carl F. Lyon, Project Manager Plant Licensing Branch IV Division of Operating Reactor Licensing Office of Nuclear Reactor Regulation

Docket No. 50-458

cc: See next page

## **DISTRIBUTION:**

PUBLIC
LPLIV r/f
RidsAcrsAcnw\_MailCTR Resource
RidsNrrDeEeeb Resource
RidsNrrDorlDpr Resource
RidsNrrDorlLpl4 Resource
RidsNrrPMFLyon Resource
RidsNrrLAJBurkhardt Resource
RidsOgcRp Resource
RidsRgn4MailCenter Resource

ADAMS Accession No: ML082880464 \*Previously concurred

DATE	10/21/20	10/16/08	11224	10-20-06	10/211/07
NAME	FLyon X	JBurkhardt*	GWilson/	MMarkley BYS ter	FLyon Joseph
OFFICE	NRR/LPL4/PM	NRR/LPL4/LA	DE/EEEB/BC	NRR/LPL4/BC	NRR/LPL4/PM

OFFICIAL AGENCY RECORD