NRC FORM 591M PAR (10-2003)	1		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201	SAFETY INS	PECTION REPORT	AND COMPLIANCE IN	ISPECTION	
LICENSEE/LOCATION INSPECTED: Cape Regional Medical Center Two Stone Harbor Boulevard Cape May Court House, New Jersey 08210 REPORT Nos 2008-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S)		4. LICENSE NUMEER(S)		5. DATE(S) OF INSPECT	ION
03011160		29-16511-01		September 26,2008	
LICENSEE:		1			
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
	Licensee's	Statement of Corre	ctive Actions for Item	4, above.	
corrective actions is made	in accordance with the will be achieved). I und	requirements of 10 CFR	ector will be taken to correct 2.201 (corrective steps alrea ritten response to NRC will be Sig	dy taken, corrective steps v	which will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Michelle Sir	nmons	Michello	Simmer	9/26/08
NRC FORM 591M PART 1	(Rev. by RI 07/06)	•	G:\Docs\Current\Insp_#ec	:ordम्स्29-16511-01.2008-00	11.591M-Part1.wpd

SUNSI Review Completed By: /RA/

X Public

X Non-Sensitive