

Void Sheet

TO: License Fee Management Branch
FROM: Region 3
SUBJECT: VOIDED APPLICATION

Control Number: 317531

Applicant: Greater Flint Imaging

License Number: 21-20320-01

Docket Number: 03018247

Date Voided: December 9, 2008

Reason for Void: The licensee failed to provide any training and experience to add an Assistant Radiation Safety Officer. Too much missing information to do anything with this request. The licensee was sent a memo requesting additional information and licensee may resubmit request under voided control 317531.

W. P. REICHHOLD
W.P. Reichhold

December 9, 2008

Signature

Date

Attachment:
Official Record Copy of
Voided Action

FOR LFMB USE ONLY

Refund Authorized and processed

No Refund Due

Fee Exempt or Fee Not Required

Comments _____ Log Completed _____

Processed by: _____