NOW-12-2008 13:36 USNRC R1 LAS

610 337 5393

P.02

NRC FORM 501M PART 1 (10-2003) 10 CFR 2.201 CAPETON DEPOSIT AND COMPLIANCE INSPECTION				
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
LICENSEE/LOCATION INSPECTED: Virginia Urology Center 9105 Stony Point Drive Richmond, Virginia 23235		2. NRCREGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 478 Afferding Road King of Pressie, PembayTvania 19405-1415		
REPORT Nos 2008-001		Vilia oi tutasia, i	minima is and is	
3. DOCKET NUMBER(S) 4. LICENSE NUMBER(S			5. DATE(S) OF INSPECT	ON
D3D-35941	45-25582-01		10/18/08, 10/29/08	(phone)
LICENSEE:				,
The inspection was an examination of the activities conducted under your license as they relate to radintion safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection constitute of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The haspection findings are as follows: 1. Based on the inspection findings, no violations were identified.				
i, basis of the appearant manage, no				
2. Previous violation(s) closed.				
3. The violation(s), specifically described to you by the inspector se non-claid violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.				
Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):				
				· CALABORA
			• •	-
				,
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
4. During this inspection certain of your activities, as described below and/or attached, were in violetion of NRC requirements and are being oited. This form is a NOTICE OF VIOLATION, which may be subject to posting in acceptation with 10 CFR 19.11.				
Contrary to 10 CFR 35.67(g), the licensee did not conduct a senti-annual physical Inventory of lodine- 125 manual brachytherapy sources in its possession, permitted by 35.406. Specifically, as of October 16, 2008, a semi-annual inventory of iodine-125 brachytherapy sources in storage was not performed.				
Licensee's Statement of Corrective Actions for Item 4, above.				
I hereby state that, within 30 days, the solions de corrective actions is made in accordance with the date when full compliance will be achieved). I und	requirements of 10 CFR 2	201 (corrective alups airea	dy, liken, corrective steps w	hich will be taken.
Title Print	ed Name	. Sig	nabre	Date
LICENSEE'S REPRESENTATIVE TERM W	Coffey	Denge C	Hey	11-12-08
NRC INSPECTOR Willie J. Lee		Wille	f. fu	10/29/2008
NRC FORM 591M PART 1 (Rev. by RI 07/06) G:\DNM5\Reference\Brank Films Word\Brank 581M-Part1 (2).doc				
SUNSI Raviaw Completed By: /RA/	Willie J. Lee	v Po	iblic x Non-Si	ensitive
	1- 11/0 V. EQQ		1101120	01.3(010