

PrairieIslandNPEm Resource

From: Richard Plasse
Sent: Wednesday, October 22, 2008 4:59 PM
To: Eckholt, Gene F.
Subject: FW: Additional Pavinich RAI
Attachments: Pavinich_additional_RAI_101508.doc

draft RAI

Hearing Identifier: Prairie_Island_NonPublic
Email Number: 271

Mail Envelope Properties (Richard.Plasse@nrc.gov20081022165900)

Subject: FW: Additional Pavinich RAI
Sent Date: 10/22/2008 4:59:13 PM
Received Date: 10/22/2008 4:59:00 PM
From: Richard Plasse

Created By: Richard.Plasse@nrc.gov

Recipients:
"Eckholt, Gene F." <Gene.Eckholt@xenuclear.com>
Tracking Status: None

Post Office:

Files	Size	Date & Time
MESSAGE	16	10/22/2008 4:59:00 PM
Pavinich_additional_RAI_101508.doc		24130

Options
Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received:

RAI B2.1.3-2

During review of LRA B2.1.3, "Operating Experience" the staff noted that there were two instances of cracking due to IGSCC of Safety Injection Accumulator Tanks. Although these cracks were repaired and the ISI program was augmented to include additional inspections, such as UT and PT, the applicant did not indicate if new activities were implemented to improve and monitor the environment to preclude IGSCC. Please provide details of any preventive activities to preclude IGSCC.