NRC FORM 591M PART 1			U.S. NUCLEAR REGULATORY COMMISSION		
(10-2003) 10 CFR 2.201	A.===				
	SAFETY INSPE	ECTION REPORT	AND COMPLI	ANCE INSPECTI	UN
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
Gritman Medic	al Center				
700 South Main Moscow, Idaho 83843			USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
Location: 700	O South Main, Mosco	ow, ID	7g.cii, 10.00		
REPORT NUMBER	2009-0				
3. DOCKET NUMBER 030-322	81	4. LICENSEE NUMBER 11-27337-0)1	5. DATE OF INSPECT	10N 02, 2009
LICENSEE:		1/55/-		L . Oblidary	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
		's Statement of C	tivo Actions for "	om A should	
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date					
LICENSEE'S REPRESENTATIVE			N N		
NRC INSPECTOR	R. Rick M	uñoz	12.1	and Marin	02/02/2009
NRC FORM 591M PART 1	(10-2003)				The state of the s