

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE SMB-00297

INFORMATION ON EXACT AMOUNTS OF MATL WAS NOT NEEDED TO EVALUATE

THIS LICENSE WAS ELIMINATED FROM CONSIDERATION

The reason for elimination was: TRANS. TO AGREEMENT STATE

Reviewer's comments concerning license SMB-00297

Although SMB-297 had expired on 4-30-62, the NRC was in the process of renewing it for the Hicksville site and General Telephone and Electronics was filing for a license at the Bayside plant when the state of New York took jurisdiction for NRC licenses in their state.

EXPERT SYSTEM EVALUATION WAS BASED ON THE
INVENTORY RECORD IN JOB 0529, BOX 01

Docket 40-00682

Licensee: SYLVANIA ELECTRIC PRODUCTS, INC., SYLCOR DIVISION

Address: WILLETS POINT BLVD. BAYSIDE L.I., NY. Zip:

THIS LICENSE WAS LISTED AS BEING TRANSFERRED TO AN AGREEMENT STATE: NY

State of operation: NY

Site used: HICKSVILLE AND BAYSIDE, NY

Disposition information present: CERTIFICATE AND LETTER

Contents of letter:

3-23-62: BAYSIDE PLANT WILL GO TO GENERAL TELEPHONE & ELECTRONICS

Text of certificate of disposition:

3-23-62: DISPOSED OF IN ACCORD WITH 10CFR20- FOR THE BAYSIDE PLANT

Matl. Transfrd to: BAYSIDE TO GENERAL TELEPHONE & ELECTRONICS

License to which transferred:

There was a reference to disposal in accordance with 10CFR20

This license was listed as expired on 04/30/62

Remarks:

JOB NUMBER: 0529 BOX NUMBER: 01

111

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE C-04029

DESCRIPTION OF ACTIVITY OR FACILITY: FABRICATION OR MANUFACT
--Type and form of materials licensed--
Material-- --Form--
NATURAL U/NORMAL U Loose material

--For evaluation purposes, amounts of the following materials were obtained--
Material-- --Form-- --Amount-- --Unit--
NATURAL U/NORMAL U LOOSE 0.4600000 lb

1. License was for loose materials, or materials handled loose
2. The loose materials on this license were not significant, and the site was eliminated from consideration on this basis.

CATEGORY FOR POTENTIAL SITE CONTAMINATION:
LICENSE ELIMINATED FROM CONSIDERATION FOR SITE CONTAMINATION
The reason is: Insignfcant matls or amts

The reason for elimination was: Insignfcant matls or amts

Reviewer's comments concerning license C-04029

THE STATE OF NEW YORK MAY HAVE TAKEN JURISDICTION FOR THIS LICENSE IN
OCT., 62.

EXPERT SYSTEM EVALUATION WAS BASED ON THE
INVENTORY RECORD IN JOB 0529, BOX 01

Docket 40-00682

Licensee: SYLVANIA-CORNING NUCLEAR CORP

Address: BAYSIDE NEW YORK

Zip:

State of operation: NY

Site used: ANYWHERE IN THE US

Disposition information present: NO DISPOSITION INFORMATION GIVEN

This license was listed as expired on 03/31/59

Remarks: FOR DISPLAY OF 200 GMS. OF NATURAL URANIUM ANYWHERE IN THE US

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE C-03700

INFORMATION ON EXACT AMOUNTS OF MATL WAS NOT NEEDED TO EVALUATE

THIS LICENSE WAS ELIMINATED FROM CONSIDERATION

The reason for elimination was: SUPERCEDED BY NEW LICENSE

EXPERT SYSTEM EVALUATION WAS BASED ON THE
INVENTORY RECORD IN JOB 0529, BOX 01

Docket 40-00682

Licensee: SYLVANIA-CORNING NUCLEAR CORPORATION

Address: BAYSIDE NEW YORK

Zip:

This license was listed as SUPERCEDED BY ANOTHER LICENSE

Contents of the new license field SMB-297 IN JUNE, 61

State of operation: NY

Site used: BAYSIDE & HICKSVILLE FAC. IN NY

Disposition information present: NO DISPOSITION INFORMATION GIVEN

Remarks: APPEARS THAT SMB-00297 TOOK OVER COVERAGE FOR THE LIC. IN JUNE, 61

JOB NUMBER: 0529 BOX NUMBER: 01
