

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

<p>1. LICENSEE</p> <p><i>American Rolep Watch Corp.</i> <i>580 Fifth Avenue</i> <i>N.Y. City</i></p>	<p>2. REGIONAL OFFICE</p> <p><i>CO. I</i></p>
<p>3. LICENSE NUMBER(S)</p> <p><i>31-5997-2</i></p>	<p>4. DATE OF INSPECTION</p> <p><i>July 18 1968</i> <i>Re-IN</i></p>
<p>5. INSPECTION FINDINGS</p> <p><input type="checkbox"/> A. No item of noncompliance was found.</p> <p><input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42</p> <p><input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42</p> <p><input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)</p> <p><input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)</p> <p><input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)</p> <p><input type="checkbox"/> G. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)</p> <p><input type="checkbox"/> H. Form AEC-3 was not properly posted. 10 CFR 20.206(c)</p> <p><input type="checkbox"/> I. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)</p> <p><input type="checkbox"/> J. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)</p> <p><input type="checkbox"/> K. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51</p> <p><input type="checkbox"/> L. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)</p> <p><input type="checkbox"/> M. Records of inventories were not maintained. 10 CFR 34.26</p> <p><input type="checkbox"/> N. Utilization logs were not maintained. 10 CFR 34.27</p> <p style="text-align: right;"><i>Alvin F. Ryan</i> (AEC Compliance Inspector)</p>	
<p>6. LICENSEE'S ACKNOWLEDGMENT</p> <p>The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.</p> <p>_____ (Date)</p> <p style="text-align: right;"><i>[Signature]</i> (Licensee Representative — Title or Position)</p>	

ORIGINAL: LICENSEE. COPIES: CO REGION CO HEADQUARTERS CO ENFORCEMENT

Inspector's Evaluation  8/23/68
American Rolex Watch Corporation
580 Fifth Ave; N.Y.C.
License No. 31-5997-2

License imports luminous timepieces
containing H^3 for sale and distribution.
Its records of quality control tests and
imports are properly maintained.
This license is properly in Category
E priority III and should be
~~scheduled for reinspection at the~~
~~standard interval July 1970~~
Clein O'Keefe

REGION I, DIVISION OF COMPLIANCE
NEWARK, NEW JERSEY

SPECIAL LIMITED INSPECTION

1. Name and address of licensee: *American Ropes
Watch Corporation
(906) 580-5111, New York, N.Y.C.*

2. Date of Inspection: *July 18, 1968*

3. Type of Inspection: *Re-insp.
Announced
reinspection*

4. License number(s), docket number(s), number and date of last amendment for each license. Category and Priority of each license:
*31-5997-2 - Amendment issued
January 5, 1967
Category E
Priority III*

5. Date of previous inspection: *9/3/65*

6. Is "Company Confidential," or proprietary, or classified information contained in report?
Yes _____ No

(Specify paragraphs)

7. Scope of inspection:
*Inspection of luminous timepieces
for s+d, phototype tests of paint, D.C.
tests of dials & hands - Annual report.*

8. *Alvin J. Ryan*
Inspector

BS
Reviewer

July 18, 1968.
Date of Report

9/12/68
Date of Review

Licensee: American Rolex Watch Corp.

Summary

Review of Certificates of prototype tests of print, quality control (vibration, bending, immersion) tests and annual reports revealed no discrepancies.

Noncompliance and Safety Items

N/A

Unusual Occurrences

~~N/A~~
none

Status of Previously Reported Noncompliance or Safety Items

N/A

Management Interview

Rene M. Girod
w/ Rene M. Girod, V.P. - no
recommendations Form C & C 591
issued.

Licensee: American Rolex Watch Corp.

DETAILS

A. Participants Rene M. Girod - V.P. Tech. Adv.
Rene M. Girod

B. Scope of Licensee Program

Import of luxurious timepieces
containing 3 for sale Distribution

C. Organization

Denton
Pres. Rene Cloutier
Ex V.P. Edward J. Meyer
Secy
Treas. Richard Lehman

D. Administrative Control

R. Lehman

E. Use of Material

As in B.

Licensee: Quevira Radio Watch Corp.

F. Facilities

Office, showrooms, shops,
storage vault

G. Equipment

N/A

H. Radiological Safety Procedures

N/A

I. Personnel Monitoring and Exposure to External Radiation

N/A

Licensee: American Radiowatch Corp.

J. Exposure of Employees to Concentrations of Radioactive Materials

N/A

K. Effluents to Unrestricted Areas

N/A

L. Disposals

N/A

M. Miscellaneous Surveys, Evaluations and Records

QC - Universal SA - 2u + B Trines
1/4/68 - 5/7/68

QC. 2u + B - Trines - 4/19 - 7/5/68

Annual report

7/3/68 - 12/31/67 - 6/30/68 - 60.262 mc H³

1/4/68 - 7/1/67 - 12/31/67 - 55.274 mc H³

9/8/67 - 12/31/66 - 6/30/67 41.841 mc H³

See N. 12/29/66 7/1/66 - 12/31/66 52.186 mc H³

Licensee: American Rolex Watch Corp.

N. Special License Conditions

licensee submitted certificate of prototype tests of new + Bentelle 7 series luminaires for the periods 1/4/68 to 7/5/68 and vibration, bending and immersion tests. Between July 1, 1967 and June 30, 1968 licensee imported 15,536 new H³ Report submitted to D.M.L.

Certificates reportedly show info showing conditions on met
PCC

O. Posting and Labeling

N/A

P. Independent Measurements

N/A

Q. Operations Observed

N/A

R. Incidents, Overexposures, Theft or Loss, Equipment Malfunction

none

Licensee: Queessee Rales Watch Corp.

S. Other Information or Continuation from Previous Paragraphs

None