



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II
SAM NUNN ATLANTA FEDERAL CENTER
61 FORSYTH STREET, SW, SUITE 23T85
ATLANTA, GEORGIA 30303-8931

June 18, 2009

Mr. Mano Nazar
Senior Vice President and Chief Nuclear Officer
Florida Power & Light Company
P.O. Box 14000
Juno Beach, FL 33408-0420

SUBJECT: TURKEY POINT - NRC SECURITY INSPECTION REPORT 05000250/2009402
AND 05000251/2009402

Dear Mr. Nazar:

On May 1, 2009, the U. S. Nuclear Regulatory Commission (NRC) completed a security baseline inspection at your Turkey Point Nuclear Plant, Units 3 and 4. The inspection covered one or more of the key attributes of the security cornerstone of the NRC's Reactor Oversight Process. The enclosed report documents the inspection results, which were discussed with Mr. W. Jefferson, and other members of your staff. A re-exit meeting was conducted by telephone on June 4, 2009 with Mr. B. Rittmer.

This inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

This report documents one finding of very low security significance (i.e., Green as determined by the Physical Protection Significance Determination Process). The finding is NRC identified. The deficiency was corrected or compensated for, and the plant was in compliance with applicable physical protection and security requirements within the scope of this inspection before the inspector left the site. The finding had a cross-cutting aspect in the area of Human Performance. H.4(c). Additionally, a licensee-identified violation, which was determined to be of very low safety significance, is listed in this report. However, because of the very low safety significance and because they are entered into your corrective action program, the NRC is treating these violations as non-cited violation(s) (NCVs) consistent with Section VI.A.1 of the NRC Enforcement Policy. If you contest these violations, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555-0001; with

Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s), this transmittal document is decontrolled.

~~LIMITED INTERNAL~~
~~DISTRIBUTION PERMITTED~~

FP&L

2

copies to the Regional Administrator Region II; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, D.C. 20555-0001; and the NRC Resident Inspector at the Turkey Point Nuclear Plant.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system, ADAMS. ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information-Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/RA/

Michael E. Ernstes, Chief
Plant Support Branch 2
Division of Reactor Safety

Docket No.: 50-250, 50-251
License No.: DPR-31, DPR-41

Enclosure: Inspection Report 05000250/2009402 and 05000251/2009402
w/Attachment: Supplemental Information

cc: See Page 3

FP&L

3

cc w/Encl:

William Jefferson, Jr.
Site Vice President
Turkey Point Nuclear Plant
Florida Power and Light Company
9760 SW 344th Street
Florida City, FL 33035

Brent Rittmer
Security Manager
Turkey Point Nuclear Plant
Florida Power and Light Company
9760 SW 344th Street
Florida City, FL 33035-1800

Robert J. Tomonto
Licensing Manager
Turkey Point Nuclear Plant
Florida Power & Light Company
9760 SW 344th Street
Florida City, FL 33035

FP&L

2

copies to the Regional Administrator Region II; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, D.C. 20555-0001; and the NRC Resident Inspector at the Turkey Point Nuclear Plant.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system, ADAMS. ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information-Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,
/RA/
 Michael E. Ernstes, Chief
 Plant Support Branch 2
 Division of Reactor Safety

Docket No.: 50-250, 50-251
 License No.: DPR-31, DPR-41

Enclosure:
 cc: See Page 3

Distribution w/encl:
 RidsNrrrPMTurkeyPoint Resource
 C. Evans, RII EICS (Part 72 Only)
 L. Slack, RII EICS (Linda Slack)
 R. Albert, NSIR (hard copy w/ encl)
 D. Riffle, NSIR (hard copy w/ encl)
 RIDSNRRDIRS
 OE Mail (email address if applicable)

PUBLIC

X PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE X NON-SENSITIVE

ADAMS: Yes ACCESSION NUMBER: _____ X SUNSI REVIEW COMPLETE

See Previous concurrence

OFFICE	RII:DRS	RII:DRS	RII:DRS	RII:DRP	DRS	
SIGNATURE	/RA/	/RA/	/RA/	/RA/	/RA/	
NAME	A. True	J. Shehee	A. Richardson	M. Sykes	M. Ernstes	
DATE	6/16/2009	6/18/2009	6/18/2009	6/16/2009	6/18/2009	
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES

OFFICIAL RECORD COPY DOCUMENT NAME: I:\PSB\SECURITY ODO REPORTS\TURKEY POINT\2009\TURKEY POINT SECURITY REPORT 2009402 ODO.DOC