



Source: Technos, 2007

LEGEND

- Magnetometer Survey Lines
- Seismic Refraction Survey Lines
- Interpreted Dike Locations
- Known Mapped Dikes
- Faults
- Magnetometer Survey Response

Progress Energy Carolinas
**Shearon Harris Nuclear Power Plant
 Units 2 and 3**
Part 2, Final Safety Analysis Report
 New Hill, North Carolina

Magnetometer Survey Results and
 Mapped Diabase Dikes

FIGURE 2.5.4-213

Rev. 0