

UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

July 9, 2009

Mr. David A. Heacock President and Chief Nuclear Officer Dominion Nuclear Connecticut, Inc. Innsbrook Technical Center 5000 Dominion Boulevard Glenn Allen, VA 23060

SUBJECT:

MILLSTONE POWER STATION, UNIT NO. 3 – CORRECTION TO ACCEPTANCE REVIEW REGARDING THIRD 10-YEAR INSERVICE

INSPECTION PROGRAM INTERVAL

Dear Mr. Heacock:

By letter dated June 25, 2009, (Agencywide Documents Access and Management System Accession No. ML091750997), the U.S. Nuclear Regulatory Commission (NRC) issued an acceptance review regarding the relief request Dominion Nuclear Connecticut, Inc. (DNC) submitted in association with the Millstone Power Station, Unit No. 3 third 10-year inservice inspection program interval. After issuance, the NRC staff discovered that the docket number for Unit 2 (50-336) was inadvertently referenced in the letter. Docket number 50-423 for Unit No. 3 should have been referenced.

We regret any inconvenience this may have caused you.

If you have any questions, please contact me at 301-415-1603.

Sincerely.

Carleen J. Sanders, Project Manager

Plant Licensing Branch I-2

Division of Operating Reactor Licensing Office of Nuclear Reactor Regulation

Docket No. 50-423

cc: Distribution via Listserv

Mr. David A. Heacock President and Chief Nuclear Officer Dominion Nuclear Connecticut, Inc. Innsbrook Technical Center 5000 Dominion Boulevard Glenn Allen, VA 23060

SUBJECT:

MILLSTONE POWER STATION, UNIT NO. 3 – CORRECTION TO ACCEPTANCE REVIEW REGARDING THIRD 10-YEAR INSERVICE

INSPECTION PROGRAM INTERVAL

Dear Mr. Heacock:

By letter dated June 25, 2009, (Agencywide Documents Access and Management System Accession No. ML091750997), the U.S. Nuclear Regulatory Commission (NRC) issued an acceptance review regarding the relief request Dominion Nuclear Connecticut, Inc. (DNC) submitted in association with the Millstone Power Station, Unit No. 3 third 10-year inservice inspection program interval. After issuance, the NRC staff discovered that the docket number for Unit 2 (50-336) was inadvertently referenced in the letter. Docket number 50-423 for Unit No. 3 should have been referenced.

We regret any inconvenience this may have caused you.

If you have any questions, please contact me at 301-415-1603.

Sincerely,

/ra/

Carleen J. Sanders, Project Manager Plant Licensing Branch I-2 Division of Operating Reactor Licensing Office of Nuclear Reactor Regulation

Docket No. 50-423

cc: Distribution via Listserv

Distribution: PUBLIC

Dide Aero Aerow MailCTD Decou

RidsAcrsAcnw_MailCTR Resource RidsNrrDciCpnb Resource RidsNrrLAABaxter Resource RidsRgn1 MailCenter Resource

RidsNrrDciCvib Resource

LPL1-2 Reading

RidsNrrDorlLpl1-2 Resource RidsNrrPMCSanders Resource

RidsOgcRp Resource RidsNrrDciCpgb Resource RidsNrrDciCptb Resource

ADAMS Accession No. ML091810999

*concurrence via e-mail

OFFICE	LPL1-2/PM	LPL1-2/LA	LPL1-2/BC
NAME	CSanders	*ABaxter	HChernoff
DATE	6/30/09	7/1/09	7/9/09

Official Record Copy