

## Southwest Research Institute® Nonconformance Report



	IDENTIF	CATION		
Submitted By: Brient, Robert D.	Date: 11-JUN-0	9	Report Number: 2009-N CR-0164	
Division: 20 - GEOSCIENCES & ENGINEERIN 01.03: QA	IG		Project Number: 14002 01.021	
Quality Program: GED (20) QAM				
Associated Report: N/A				
Defect Code: Failure to follow procedure				
10 CFR Part 21 Reportable: No				
Description of the Nonconformance:				
971, 788	· ·		orious balance (SN 12809099)that was used to	
ued To: Robert Brient		Response Due Date: 18-JUN-09		
SwRI cc: Patrick, Wesley C. (20), Pearcy, English	sh C. (20), Sagar, Budhi (2	0), Walter, Gary	y R (20)	
	RESPO	NSE(S)		
Disposition: Rework to original specification				
Customer Approval of Disposition Required? N	0			
Proposed Action to Address Nonconformance:				
Corrected during audit. Notebook corre	ections were made by the o	riginal authors.		
Response By: Brient, Robert D.	Date: 11-JUN-09		arget Date for Action: 11JUN-09	
	APPRO	OVALS		
Management Approval: Mackin, Patrick C.		Date: 16-JUN-09		
QA Approval: Mackin, Patrick C.		Date: 16-JUN-09		
	VERIFIC	CATION		
Verification of Action Taken: Corrected during audit				
Verified By: Mackin, Patrick C.	erified By: Mackin, Patrick C.		<b>Date:</b> 16–JUN–09	

© 2006 Southwest Research Institute ® Quality Reporting System, Release 1.5, Form: NCR

06/16/09 10:33:58