

Mr.
President and CEO
AmerGen Energy Company, LLC
200 Exelon Way, KSA 3-E
Kennett Square, PA 19348

SUBJECT: OYSTER CREEK GENERATING STATION - NRC INSPECTION REPORT
05000219/200X00X

Dear Mr. :

During the period of [redacted] the NRC completed an inspection of the on site license renewal activities of your Oyster Creek Generating Station during the last planned outage. The inspection continued in our Region 1 office until [redacted]. The enclosed report documents the results of the inspection, which were discussed on [redacted] with members of your staff in a telephone conference observed by representatives from the State of New Jersey.

[redacted] (b)(5) [redacted] Inspection Procedure 71003

Ex 5

"Post-Approval Site Inspection for License Renewal" and observed Oyster Creek license renewal activities during the last planned outage prior to entering the period of extended operation.

Inspection Procedure 71003 verifies license conditions added as part of the renewed license, license renewal commitments, selected aging management programs, and license renewal commitments revised after the renewed license was granted, are implemented in accordance with Title 10 of the *Code of Federal Regulations* (CFR) Part 54, "Requirements for the Renewal of Operating Licenses for Nuclear Power Plants". [redacted] (b)(5)

Ex 5

[redacted] (b)(5) [redacted] The enclosed report records the inspector's observations, absent any conclusions of adequacy, pending the final decision of the Commissioners on the appeal of the renewed license.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

Richard Conte, Chief
Engineering Branch 1
Division of Reactor Safety

Docket No. 50-219
License No. DPR-16

N/74

SUMMARY OF FINDINGS

IR 05000219/200X00X; , Oyster Creek Generating Station; Inspection of the ongoing license renewal activities at Oyster Creek Generating Station.

This inspection of license renewal activities was performed by three regional office engineering inspectors. The inspection was conducted in accordance with Inspection Procedure 71003 "Post-Approval Site Inspection for License Renewal" (b)(5)

(b)(5) The report records the inspector's observations, absent any conclusions of adequacy, pending the final decision of the Commissioners on the appeal of the renewed license.

25

4. OTHER ACTIVITIES (OA)

4OA2 Other - License Renewal

a. Inspection Scope

This inspection was conducted by NRC Region I based inspectors in order to observe Oyster Creek's continuing license renewal activities during the last planned outage prior to entering the extended period of operation. The inspection team selected a number of systems for review, using the NRC accepted guidance and their importance in the license renewal application process, in order to gauge the plant's state-of-readiness to enter the extended period of operation.

[

(b)(5)

]

(b)(5)

The

REAS

inspector's recorded important observations, and reported them absent any conclusions of adequacy, pending the final decision of the Commissioners on the appeal of the renewed license.