NRC FORM 591M PART 1 (4-2008)		U.S. NUCLEAR REGULATORY COMMISS	ION
10 CFR 2.201	SPECTION REPORT	AND COMPLIANCE INSPECTION	
1. LICENSEE/LOCATION INSPECTED: Core Engineering & Consulting, LLC 115 West Beebe Avenue, Chamber REPORT No 2009-00	rlain, South Dalesta	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
3. DOCKET NUMBER	4. LICENSE NUMBER	5. DATE OF INSPECTION	
030-37747	40-29299-01	June 22, 2009	
Regulatory Commission (NRC) rules and regula procedures and representative records, intervier and representative records, intervier 1. Based on the inspection findings, rows, and consideration of the inspection	tions and the conditions of which personnel, and observed to violations were identified to you by the inspectative action was or is being iscussed involving the folking the total activities, as described	r license as they relate to radiation safety and to compliance with the Nuclot your license. The inspection consisted of selective examinations of oservations by the inspector. The inspection findings are as follows: ad. tor as non-cited violations, are not being cited because they were self-g taken, and the remaining criteria in the NRC Enforcement Policy to dowing requirement(s) and Corrective Action(s): below and/or attached, were in violation of NRC requirements and are be a subject to posting in accordance with 10 CFR 19.11.	
I hereby state that, within 30 days, the action corrective actions is made in accordance with t	s described by me to the in he requirements of 10 CFF	rective Actions for Item 4, above. inspector will be taken to correct the violations identified. This statement R 2.201 (corrective steps already taken, corrective steps which will be taken.	ken,
Title Pri	I understand that no furthen the Name	er written response to NRC will be required, unless specifically requested Signature Date	d.
REPRESENTATIVE			
NRC INSPECTOR Jason M. Razo		(b) W 1/m 6-22-6	29
NRC FORM 591M PART 1 (Rev. by RIV 3/09) Non-Public Sensitive – Se		DNMS\!NMps(!Razo\inspections\South Dakota\2009-06\Core Engr Part1	.doc