

### Lessons-Learned Program Effectiveness Reviews

Title	Org.	Assignment	Delivery	LLOB Review
Loss of Vital AC Power and the Residual Heat Removal System During Mid-Loop Operations at Vogtle Unit 1 on March 20, 1990” (NUREG-1410, June 1990)	NRR	January 27, 2006 ML060110310	April 13, 2006 ML060970206	July 14, 2006 ML061950312 (*by a team chartered in January 2005)
Indian Point 2 Steam Generator Tube Failure Lessons Learned Task Group” (Newberry memo dated October 23, 2000) (ML020710276, ML020320416)	NRR			
Potential Criticality Accident at the General Electric Nuclear Fuel and Component Manufacturing Facility, May 29, 1991” (NUREG-1450, August 1991)	NMSS		April 13, 2006 ML060970383	
Loss of an Iridium-192 Source and Therapy Misadministration at Indiana Regional Cancer Center, Indiana, Pennsylvania on November 16, 1992” (NUREG-1480, February 1993)	NMSS FSME	January 27, 2006 ML060110310 & March 12, 2007 ML070600431	April 13, 2006 ML060970383 & Jan. 14, 2008 via E-mail	
Unauthorized Forced Entry into the Protected Area at Three Mile Island Unit 1 on February 7, 1993” (NUREG-1485, April 1993)	NSIR	January 27, 2006 ML060110310	May 16, 2006 ML060510076	
Effect of Hurricane Andrew on Turkey Point Generating Station from August 20-30, 1992” (NUREG-1474, March 1993 and IN 95-53)	NSIR			
Loss of Main and Auxiliary Feedwater Event at the Davis-Besse Plant on June 9, 1985 (NUREG-1154, July 1985)(ML063560434)	NRR	March 12, 2007 ML070600431	May 30, 2008	July 24, 2008 ML TBD

\*MD 6.8 was issued in August 2006 and the LLOB was chartered in September 2006 (ML062510102).