RAS C-115

U.S. NRC In re DAVID GEISEN GEICHN Exhibit #_ Docket # 1A-05-052	5	• •
Docket # 1A-05-052	ادور	i i
Date Marked for ID: 12/10, 2008 (Tr. p. 4.	<u>729</u>)
Date Offered in Ev: 12/10, 2008 (Tr. p. 1	534)
Through Witness/Panel: N/A		

Prasoon K. Goyal/TE/FirstEnergy

Rodney M. Cook/FirstEnergy@FirstEnergy, Andrew J. Siemaszko/FirstEnergy@FirstEnergy

REJECTED WITHDRAWN

Frank W. Kennedy/TE/FirstEnergy@FirstEnergy, Mark A. McLaughlin/TE/FirstEnergy@FirstEnergy@FirstEnergy. D.

Subject: Re: 12RFO RV Head Inspection - Bulletin 2001-01 response

12/10

Date: 8/22/2001 13:2:541010

I think we need to make sure what 90% inspected means. Does this 90% inspected meams prior to cleaning the head o after the head was cleaned. I would think prior to head cleaning. Andrew please clarify.

Rodney M. Cook

08/22/01 10:13 AM

To; Wuckko/TE/FirstEnergy@FirstEnergy, Dale L. Miller/TE/FirstEnergy@FirstEnergy Prasoon K. GoyaVTE/FirstEnergy@FirstEnergy, Mark A. McLaughlin/TE/FirstEnergy@FirstEnergy, Andrew J. Siemaszko/FirstEnergy@Fin David H. Lockwood/TE/FirstEnergy @ FirstEnergy, Frank W. Kennedy/TE/FirstEnergy @ First 12RFO RV Head Inspection Subject: 2001-01 response

in response to questions I have received concerning the definition of the "majority of the nozzles" that were inspected during 12RFO, Andrew stated that aproximately 90% were inspected. This will be used in the Bulletin response.


Rod Cook x7782

> DOCKETED **USNRC**

September 9, 2009 (11:00am)

OFFICE OF SECRETARY **RULEMAKINGS AND** ADJUDICATIONS STAFF

S14D-05262



NRC007-2610

TEMPLATE = SECY-028

1502