

TRANSMISSION VERIFICATION REPORT

TIME : 08/25/2009 15:56  
NAME : USNRC RIII  
FAX : 6308299782  
TEL :  
SER.# : 000A7J925774

DATE, TIME 08/25 15:55  
FAX NO./NAME 87346629224  
DURATION 00:00:42  
PAGE(S) 02  
RESULT OK  
MODE STANDARD  
ECM

NRC FORM 386 (RIII)  
(4-2004)



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
2443 Warrenville Road, Suite 210  
Lisle, Illinois 60532-4352

TELEFAX TRANSMITTAL

DATE: 08/25/2009 NUMBER OF PAGES: 2  
(including this page)

SEND TO: Cari Dzanbazoff, RSO (consultant)

LOCATION: Cardiovascular Associates

FAX NUMBER: 734 - 662 - 9224  **VERIFY BY CALLING SENDER**

FROM: Jose Macatangay  
(SENDER)

TELEPHONE NUMBER: 630 - 829 - 9892 FAX NUMBER: 630 - 515 - 1078

If you do not receive the complete fax transmittal, please contact the sender as soon as possible at the telephone number provided above.

MESSAGE

*Cari*



**JOSE D. MACATANGAY**  
**MATERIALS LICENSING BRANCH**  
**UNITED STATES NUCLEAR REGULATORY COMMISSION**

REGION III  
2443 WARRENVILLE ROAD STE 210  
LISLE, ILLINOIS 60532-4352  
OFFICE: (630)-829-9892 FAX: (630) 515-1078

**CONVERSATION RECORD**  
**ACTUALLY FAXED?**

Yes

TIME

DATE

08/25/2009

NAME OF PERSON(S) CONTACTED

Cari Dzanbazoff, RSO (consultant)

ORGANIZATION

Cardiovascular Associates

TELEPHONE NO

O: 734-662-3197

F: 734-662-9224

SUBJECT

License No.: 21-15166-01

Control No.: 318282

SUMMARY

We have reviewed your amendment request dated June 10, 2009, and find that we need additional information as follows:

1. Per your submittal, sealed sources were possessed under this license. Specifically, the leak test certificate for Co-57 is missing. Please submit a copy of the latest leak test result for the Co-57 sealed source.

We will be unable to continue processing your request until we receive this information. In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically in the NRC Public Document Room or from the Publicly Available Record (PARS) component of NRC's document system (ADAMS) accessible from the NRC Website at <http://www.nrc.gov/reading-rem/adams.html>.

ACTION REQUIRED

Please submit a written response within 14-days or contact me to arrange an alternate response date. Be sure to reference control number 318282 to facilitate correct processing of your response.

If we do not receive a written response within 14-days, please note that we may void this request in order to enable you to prepare a response without time constraints. This would be done without prejudice to the resubmission of your request at a later date. Upon receipt of your response we will resume our review. Address your written response to my attention at the above address.

Please note that a "Void" is an administrative procedure that puts your amendment request "On Hold" (takes it out of our active casework database) until you reactivate it via submission of a written response. Upon receipt of your written response we will resume our review.


**PLEASE DIRECT ANY QUESTIONS YOU MAY HAVE TO ME AT (630) 829-9892.**

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

Jose Macatangay



August 25, 2009

*C. Casey 9/10/09 - final review.*

TRANSMISSION VERIFICATION REPORT

TIME : 08/25/2009 12:13  
 NAME : USNRC RIII  
 FAX : 6308299782  
 TEL :  
 SER.# : 000A7J925774

DATE, TIME 08/25 12:13  
 FAX NO./NAME 87345629224  
 DURATION 00:00:27  
 PAGE(S) 01  
 RESULT OK  
 MODE STANDARD  
 ECM

**JOSE D. MACATANGAY**  
**MATERIALS LICENSING BRANCH**  
**UNITED STATES NUCLEAR REGULATORY COMMISSION**  
 REGION III  
 2443 WARRENVILLE ROAD STE 210  
 Lisle, ILLINOIS 60532-4352  
 OFFICE: (630)-829-9892 FAX: (630) 515-1078

**CONVERSATION RECORD** | TIME | DATE  
**ACTUALLY FAXED?** Yes | | **08/25/2009**

NAME OF PERSON(S) CONTACTED ORGANIZATION TELEPHONE NO.  
 Cari Dzanbazoff, RSO (consultant) Cardiovascular Associates O: 734-662-3197  
 F: 734-662-9224

SUBJECT  
 License No.: 21-15166-01 Control No.: 318282

**SUMMARY**  
 We have reviewed your amendment request dated June 10, 2009, and find that we need additional information as follows:

1. Per your submittal, sealed sources were possessed under this license. Specifically, the leak test certificate for Co-57 is missing. Please submit a copy of the latest leak test result for the Co-57 sealed source.

We will be unable to continue processing your request until we receive this information. In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically in the NRC Public Document Room or from the Publicly Available Record (PARS) component of NRC's document system (ADAMS) accessible from the NRC Website at <http://www.nrc.gov/reading-rem/adams.html>.

**ACTION REQUIRED**  
 Please submit a written response within 14-days or contact me to arrange an alternate response date. Be sure to reference control number 318282 to facilitate correct processing of your response