

ESBWR DCD Tier 2 Chapter 10
26A6642BF Revision 5 to Revision 6 Change List

Item	Location	Description of Change
1.	Entire Chapter	Global chapter editorial changes to correct misspelling and grammar, spell out or integrate acronyms where appropriate, and update references as needed and where required.
2.	T10.1-1, Main Condenser entry, Standard Plant Value column	Values updated to be consistent with current design calculations.
3.	F10.1-1	Figure updated to reflect reroute of #7 heater drains to be consistent with current design.
4.	S10.2.3.2	Added 10 $\sqrt{\text{mm}}$ (2 $\sqrt{\text{in}}$) as per NRC Standard Review Plan 10.2.3, Fracture Toughness Section.
5.	S10.3.3, 2 nd para., 1 sent.	Updated 10 CFR reference in response to RAI 7.5-8.
6.	S10.4.3.3, 2 nd para., 5 th sent.	Updated incorrect cross reference in response to NRC comment.
7.	S10.4.7.2.2.3, 1 st para., 2 nd & 3 rd sent.	Reroute # 7 heater drains to be consistent with current design.
8.	T10.4.3	Values updated to be consistent with current design calculations.
9.	T10.4-1, Main Condenser entry, Standard Plant Value column	Values updated to be consistent with current design calculations and Notes added for consistency.
10.	F10.4-6a	Figure updated to correct check valve orientation on extraction to #4 feedwater heater.
11.	F10.4-7b	Figure updated to reflect reroute of #7 heater drains to be consistent with current design.