

***NATIONAL PHYSICS CONSULTANTS, Ltd.***

***Date:*** 10/23/09

***To:*** Jose Macatangay

***From:*** C. Kelly Stoneberg, Consultant

***Subject:*** Alliance Health Care Services license renewal

Mr. Macatangay,

The following information is for:

Alliance Health Care Services  
License # 34-26286-02  
Control # 318173

10/23/09

Jose Macatangay  
U.S. Nuclear Regulatory Commission  
Region III  
2443 Warrenville Road, Suite 210  
Lisle, Illinois 60532-4352

Control Number: 318173

License #34-26286-02


Dear Jose,

In response to your fax on 10/19/09. I have addressed the following items from NUREG 1556, Vol. 9, Rev. 2, Appendix V in regards to the Alliance Health Care Services radioactive materials license renewal.

- There is no base location. All of the trucks are mobile.
- There is no off street parking of the trucks. All of the trucks are parked at client sites when not in use.
- The delivery of byproduct material to the truck will only occur only when licensee personnel are present on the truck.
- In the driver compartment the exposure rates are no greater than background.
- None of the trucks are ever located in residential areas.
- Performed surveys show that exposure rates do not exceed 2 mrem in any one hour nor 100 mrem per year.
- All licensee personnel are supervised by an authorized user.
- No preparation of radioactive materials are performed on the trucks. Only unit doses are used.
- The technologists, drivers and all other personnel frequenting the truck receive radiation safety training annually.
- The technologists and drivers receive DOT training at the minimum of every three years.
- All radioactive waste is stored on the trucks.
- If the trucks become disabled, all radioactive materials are secured within the truck.
- All patients administered PET materials meet the criteria for release on 35.75.

Please contact me if additional information is needed at (888) 456-5255.

Sincerely,



C. Kelly Stoneberg