

Ennis, Rick

From: Ed Miller
Sent: Tuesday, June 02, 2009 3:15 PM
To: Keith Hoffman
Cc: Rick Ennis
Subject: Response to Congressman Adler

Keith,

I spoke with John Richmond and he raised a good question. The responses that I drew from the Markey letter discuss the ASME Code requirements, which may or may not be applicable to the piping that failed at Oyster Creek (The Indian Point issue involved a safety-related system). If you'd like, I can set up a call with him. Just let me know.

Ed

B-45

Received: from HQCLSTR02.nrc.gov ([148.184.44.77]) by TWMS01.nrc.gov
([148.184.200.145]) with mapi; Tue, 2 Jun 2009 15:15:03 -0400
Content-Type: application/ms-tnef; name="winmail.dat"
Content-Transfer-Encoding: binary
From: Ed Miller <Ed.Miller@nrc.gov>
To: Keith Hoffman <Keith.Hoffman@nrc.gov>
CC: Rick Ennis <Rick.Ennis@nrc.gov>
Date: Tue, 2 Jun 2009 15:15:01 -0400
Subject: Response to Congressman Adler
Thread-Topic: Response to Congressman Adler
Thread-Index: Acnjtm1QFiBymMrTQsWPBVfbM9EE1Q==
Message-ID:
<3DF2506A7257014AAC5857E5E852DEAC07553C1A87@HQCLSTR02.nrc.gov>
Accept-Language: en-US
Content-Language: en-US
X-MS-Has-Attach:
X-MS-Exchange-Organization-SCL: -1
X-MS-TNEF-Correlator:
<3DF2506A7257014AAC5857E5E852DEAC07553C1A87@HQCLSTR02.nrc.gov>
MIME-Version: 1.0