



P.O. Box 185
Twin Lakes Road
North Branford, CT 06471

November 2, 2009

U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Document Control Desk

Cc: Director, Division of Engineering

Subject: Request for extension of response to Inspection Report No. 99901382/2009-201.

Prime Technology LLC requests a thirty days extension in reference to Inspection Report No. 99901382/2009-201.

Prime Technology LLC has been backlogged with priority contracts to support the U.S. Navy, Department of Defense (DOD), and the British Ministry of Defense (MOD) in support of the war effort.

Since the inspection of August 11 – 14th Prime Technology LLC has restructured the staff in the Quality Department. Two test department employees now report to the Production Manager instead of the Quality Manager. The Test Engineer now reports to the Chief Technology Officer instead of the Quality Manager. The hiring of a Quality Engineer has been authorized and an offer to a candidate shall soon be tendered. The Quality organization shall consist of a Quality Engineer, Receiving / In-Process Inspector, and a Final Inspector reporting to the Quality Manager.

The restructuring shall allow the Quality Department to focus on corrective actions required by previous audits and insure Quality requirements are fulfilled.

Sincerely,

Paul Grabek
Quality Manager
Prime Technology LLC

TE09
LIR