




Research Reactor Center  
University of Missouri-Columbia

1513 Research Park Drive  
Columbia, MO 65211  
(573) 882-4211



**FAX**

11/10/09

**To:** *Rulemaking & Directives Branch* **From:** Margee P. Stout  
*573-882-5296*

---

**Fax:** *301-492-3446* **Pages:** *2* **Including Cover Sheet**

---

**Phone:** **Phone:**

---

**Re:** *Comments on DG-2001*

- Urgent       For Review       Please Comment       Please Reply

*9/15/09*  
*74 FR 47280*

*(1)*

RECEIVED

NOV 10 10 43 AM '09

RULES AND DIRECTIVES  
 BRANCH  
 1513 PC

Faxed From: Research Reactor Mail Room

*F-RFDS = ADM-03*

*SONSI Review Comp ltr  
 Template = ADM-013*

*Call = R. Jervy (ras)*



# Research Reactor Center

University of Missouri

1513 Research Park Drive  
Columbia, MO 65211

PHONE 573-882-4211

FAX 573-882-6360

WEB <http://web.missouri.edu/~murrwww>

November 10, 2009

Rulemaking and Directives Branch  
Mail Stop: TWB-05-B01M  
Office of Administration  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

RECEIVED  
2009 NOV 10 AM 11:42  
RULES AND DIRECTIVES  
BRANCH  
15/11/09

Re: Comments on DG-2001, Quality Assurance Program Requirements for Research and Test Reactor

This letter is sent in response to the solicitation of comments that was printed in the Federal Register, Volume 74, No.177, September 15, 2009. The University of Missouri Research Reactor supports the revision of Regulatory Guide 2.5 (May 1977) and recommends that the NRC continue to endorse the ANSI/ANS 15.8-1995; reaffirmed 2005 document "Quality Assurance Program Requirements for Research Reactors" as the basis for the revision.

Sincerely,

Ralph A. Butler, Director  
University of Missouri Research Reactor