

NORTHEASTERN VERMONT
REGIONAL HOSPITAL

P-7

Hospital Drive
St. Johnsbury, VT 05819

44-28802-01
03032980

Phone # 802 - 748 - 7900

Fax # 802 - 748 - 7549



RADIOLOGY FAX TRANSMISSION

DATE: DEC 9, 2009

TO: T. Thompson, NAC


RE MAIL CONTROL NO. 144298

FROM: J. McGeorge, NAIT

SUBJECT: FINAL SURG RESULTS, UT-RADIOLOGISTS

Number of pages, including cover: 3

COMMENTS:



VERMONT RADIOLOGISTS
 620 HINESBURG ROAD
 SO. BURLINGTON, VT 05403

FINAL

DAILY RADIATION SURVEYS

		MON.	TUES.	WED.	THUR.	FRI.
	DATE		11/17/09			
	METER		Lucille 14C			
POS. LOCATION	TECH.		J. McGehee			
	TRIGGER LEVEL	READING	READING	READING	READING	READING
	MR/HR	MR/HR	MR/HR	MR/HR	MR/HR	MR/HR
	BACKGROUND ()		0.02			
1	BENCH/CAL.	2.0 MR/HR	<0.02			
2	DECAY AREA	2.0 MR/HR	<0.02			
3	SINK	2.0 MR/HR	<0.02			
4	SEALED SOURCES	2.0 MR/HR	<0.02	transferred to Pharmacy Dept		
5	INJECT. STAND	2.0 MR/HR	<0.02			
6	CONSOLE	2.0 MR/HR	<0.02			
7	GARBAGE	.05 MR/HR	<0.02			
8	BATHROOM	.05 MR/HR	<0.02			
9	HALLWAY	0.5 MR/HR	<0.02			
10	FLOOD SOURCE AREA	2.0 MR/HR	<0.02			

1. Measurements are to be made approximately 1cm from the area with the probe shield open.
2. If trigger levels are exceeded, call the RSO immediately.
3. RSO must review surveys monthly.

RSO *[Signature]*

Vermont Radiologists
620 Hinesburg Road
So. Burlington, Vt 05403
Weekly Contamination Survey

FINAL

Instrumentation
Caprac SN#221

		Date	11/17/2009		
		Well	CAPRAC		
		Tech.	J. McKeown NRT		
Pos	Location	Trigger Levels			
	Background - 10mW	500CPM	404		
1	Bench & Calibrator	2000DPM	0		
2	Decay Area	2000DPM	0		
3	Sink	2000DPM	0		
4	Sealed Source	2000DPM	0		
5	Inject. Stand	2000DPM	0		
6	Console	2000DPM	0		
7	Garbage	2000DPM	0		
8	Bathroom	200DPM	0		
9	BACKGROUND \bar{p}	200DPM	409 cpm		

1. IF TRIGGER LEVELS ARE EXCEEDED, CALL RSO IMMEDIATELY.
2. SURVEY FORMS MUST BE SIGNED BY RSO MONTHLY

RSO:

H. McKeown