POWER AUTHORITY OF THE STATE OF NEW YORK

京都寺である。す。

10 COLUMBUS CIRCLE RENEW EXCHANGE UNIT

TRUSTEES

-41.1


JOHN S. DYSON CHAIRMAN

GEORGE L. INGALLS
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

FREDERICK R. CLARK



October 31, 1980 IPN-80-101 GEORGE T. BERRY
PRESIDENT & CHIEF
OPERATING OFFICER

JOHN W. BOSTON

EXECUTIVE VICE

PRESIDENT & DIRECTOR

OF POWER OPERATIONS

JOSEPH R. SCHMIEDER EXECUTIVE VICE PRESIDENT & CHIEF ENGINEER

LEROY W. SINCLAIR SENIOR VICE PRESIDENT & CHIEF FINANCIAL OFFICER

THOMAS R. FREY
SENIOR VICE PRESIDENT
& GENERAL COUNSEL

Director of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Attention: Mr. Steven A. Varga, Chief

Operating Reactors Branch No. 1

Division of Licensing

Subject:

Indian Point 3 Nuclear Power Plant

Docket No. 50-286

Mid-Cycle Steam Generator Inspection

Dear Sir:

In accordance with the provisions of Item 2.J to Facility Operating License No. DPR-64, the Authority hereby submits the attached results of the inspection performed on Steam Generator No. 32 during the current mid-cycle outage. This inspection was performed utilizing the plan detailed in the Authority's August 28, 1980 letter (IPN-80-79) to you on the subject item.

The results presented in this report were verbally presented to members of your staff in phone conversations on October 16, 17 and 20, 1980. In a phone conversation on October 20, 1980, your Mr. L. Olshan indicated that the NRC's technical review of the inspection results were in general agreement with what the staff expected to see from this mid-cycle inspection. Your staff indicated that the results of the testing performed on Steam Generator No. 32 satisfies the requirements of Item 2.J for the mid-cycle steam generation inspection at Indian Point 3.

Very truly yours,

Senior Vice President Nuclear Generation

cc: See attached

R

400/ s //

8011050 453

U. S. Nuclear Regulatory Commission

-2-

cc: Mr. T. Rebelowski

Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38

Buchanan, New York 10511