

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200

GEORGE T. BERRY
PRESIDENT & CHIEF
OPERATING OFFICER

JOHN W. BOSTON
EXECUTIVE VICE
PRESIDENT—PROCEDURES
& PERFORMANCE

JOSEPH R. SCHMIEDER
EXECUTIVE VICE
PRESIDENT & CHIEF
ENGINEER

LEROY W. SINCLAIR
SENIOR VICE PRESIDENT
& CHIEF FINANCIAL
OFFICER

THOMAS R. FREY
SENIOR VICE PRESIDENT
& GENERAL COUNSEL

TRUSTEES

JOHN S. DYSON
CHAIRMAN

GEORGE L. INGALLS
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

FREDERICK R. CLARK



October 15, 1981
IPN-81-77

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Emergency Procedures and Training
for Station Blackout Events



Dear Sir:

This letter corrects a typographical error which appeared in our September 16, 1981 letter (IPN-81-70) on the same subject.

The Authority stated in the above letter that IP-3 emergency procedure PEP-EL-1 was being revised to provide operator direction in the event of a loss of "offsite" power. This was an error and should have read, "[t]he Authority, however, is revising this procedure to provide operator direction in the event of a loss of onsite power as well." (Emphasis supplied).

Please accept our apologies for any inconvenience which this typographical error may have caused.

Very truly yours,


J. P. Bayne
Senior Vice President
Nuclear Generation

cc: attached

A050
S/10

8110200574 811015
PDR ADDCK 05000286
F PDR

cc: Mr. T. Rebelowski
Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

Mr. Ron Barton
United Engineers & Constructors, Inc.
30 S. 17th Street
Philadelphia, Pa. 19101