

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



March 15, 1982
IP-JAS-429

Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20055

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286

NUREG-0737 Item II.E.1.2
Auxiliary Feedwater System Evaluation

Dear Mr. Varga:


This letter provides the information requested during the March 5, 1982 teleconference between the Authority and the NRC staff and their consultants, the Franklin Research Institute. The Authority provides with the attached documents the following requested information:

- POP 1.1 Plant Operating Procedure, Plant Heatup From Cold Shutdown Condition
- SOP-FW-4 Standard Operating Procedure, Auxiliary Feedwater System Operation
- UE&C drawings: 9321-LL-31183 sheet 6.
9321-LL-31403 sheets 7 and 12.

This letter also confirms the March 10, 1982 discussion between Mr. Marc Wigdor of your staff and Mr. John Schivera of the Authority concerning scheduled maintenance on the Auxiliary Feedwater System flow transmitters. Technical Specifications, Table 4.1-1 requires that the Auxiliary Feedwater Systems flow transmitters be calibrated each refueling outage.

Should you have any further questions, please contact us.

Very truly yours,


John C. Brons
Resident Manager

Attachments

A046
S/11

8203220359 820315
PDR ADDCK 05000286
PDR