

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200

TRUSTEES

JOHN S. DYSON
CHAIRMAN

GEORGE L. INGALLS
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

FREDERICK R. CLARK



September 30, 1982
IPN-82-65

LEROY W. SINCLAIR
PRESIDENT & CHIEF
OPERATING OFFICER

WALTER T. KICINSKI
FIRST EXECUTIVE
VICE PRESIDENT &
CHIEF ADMINISTRATIVE
OFFICER

JOSEPH R. SCHMIEDER
EXECUTIVE VICE
PRESIDENT & CHIEF
ENGINEER

JOHN W. BOSTON
EXECUTIVE VICE
PRESIDENT PROCEDURES
& PERFORMANCE

THOMAS R. FREY
SENIOR VICE PRESIDENT
& GENERAL COUNSEL

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
NUREG-0737-Item III.A.1.2

Dear Sir:

The Authority has installed, as stated in our letter dated June 4, 1982 (IPN-82-44), CRT terminals in the control room and the interim Technical Support Center (TSC). However, the installation of a CRT terminal in the Emergency Operations Facility (EOF) and the video surveillance system will be completed by the end of the current refueling outage.

Should you or your staff have any questions, please contact Mr. P. Kokolakis of my staff.

Very truly yours,

J. P. Bayne
Senior Vice President
Nuclear Generation

cc: attached

A046

cc: Resident Inspector's Office
Indian Point Unit 3
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

Mr. Ron Barton
United Engineers and Constructors, Inc.
30 S. 17th Street
Philadelphia, PA 19101