

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200

TRUSTEES

JOHN S. DYSON
CHAIRMAN

GEORGE L. INGALLS
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

JAMES L. LAROCCA



LEROY W. SINCLAIR
PRESIDENT & CHIEF
OPERATING OFFICER

WALTER T. KICINSKI
FIRST EXECUTIVE
VICE PRESIDENT &
CHIEF ADMINISTRATIVE
OFFICER

JOSEPH R. SCHMIEDER
EXECUTIVE VICE
PRESIDENT & CHIEF
ENGINEER

STEPHEN L. BAUM
SENIOR VICE PRESIDENT
& GENERAL COUNSEL

March 7, 1983
IPN-83-19

Director of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Safety and Relief Valve Failures and Challenges


Dear Sir:

This letter is provided in accordance with the requirement of Item II.K.3.3. of NUREG-0737 to submit an annual report concerning safety and relief valves failures and challenges.

Subsequent to a review of the Significant Occurrence Report (SOR) file, the Authority has determined that Indian Point 3 has experienced no failures or challenges of these valves during calendar year 1982.

Should you or your staff have any questions, please contact Mr. P. Kokolakis of my staff.

Very truly yours,



J. P. Bayne
Executive Vice President
Nuclear Generation

cc: Resident Inspector's Office
Indian Point 3
U.S. Nuclear Regulatory Commission
P. O. Box 66
Buchanan, New York 10511

8303150437 830307
PDR ADOCK 05000286
R PDR

A048