

123 Main Street
White Plains, New York 10601
914 681.6240



John C. Brons
Executive Vice President
Nuclear Generation

March 15, 1991
IPN-91-006

U.S. Nuclear Regulatory Commission
Mail Station P1-137
Washington, D.C. 20555

Attn: Document Control Desk

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Inservice Inspection Report
For Cycle 7/8 Refueling Outage


Dear Sir:

This letter submits the Inservice Inspection Report as required by Article IWA-6000 of Section XI of the ASME Boiler and Pressure Vessel Code.

Attachment I is a report of the inservice inspection conducted during Cycle 7/8 refueling outage. This inspection is the first examination of the second 40-month period of the Second 10-Year Indian Point 3 Inservice Inspection Program. The report consists of extracts from Tabs A, B, and C of the Final Weld and Component Examination Report.

If you have any questions regarding this matter, please contact Mr. P. Kokolakis.

Very truly yours,


John C. Brons
Executive Vice President
Nuclear Generation

Encl.

cc: U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

9103210286 910315
PDR ADOCK 05000286
Q PDR

A047
11

Resident Inspector's Office
Indian Point 3
U.S. Nuclear Regulatory Commission
P.O. Box 337
Buchanan, New York 10511

Mr. J. D. Neighbors, Sr. Project Manager
Project Directorate I-1
Division of Reactor Projects-I/II
U.S. Nuclear Regulatory Commission
Mail Stop 14B2
Washington, D.C. 20555