Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914-736-8000



March 12, 1991 IP3-91-021 IPO-91-043L

Docket No. 50-286 License No. DPR-64

Mr. Thomas T. Martin Region I Administrator U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Dear Mr. Martin:

In accordance with 10CFR50.4(b)(5), one (1) copy of the most recent revisions to our Emergency Plan/Procedures has been sent to the NRC Document Control Desk in Washington, D.C. Two (2) copies have been sent to your office, Emergency Preparedness Section, and one (1) copy has been sent to the IP-3 Resident Inspector.

These changes have been evaluated against 10CFR50.54(q) and have been determined not to decrease the effectiveness of the Indian Point 3 Emergency Plan. The Plan and Procedures, as changed, continue to meet the standards of 10CFR50.47 and Appendix E.

Sincerely

Joséph E. Russell Resident Manager

Und

Indian Point No. 3 Nuclear Power Plant

JER/DB/lat

cc:

Document Control Desk (original) U.S. Nuclear Regulatory Commission

Washington, D.C. 20555

Resident Inspector's Office

Indian Point No. 3

U.S. Nuclear Regulatory Commission

P.O. Box 337

Buchanan, New York 10511