

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



**New York Power
Authority**

John H. Garrity
Resident Manager

June 14, 1993
IPN-93-061

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station PI-137
Washington, D.C. 20555

SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Licensee Event Report LER 92-015-01,
"Reactor Trip Caused By Independent
Instrumentation/Control Failures."

Dear Sir:

The attached Licensee Event Report LER 92-015-01 is hereby submitted in accordance with the requirements of 10CFR50.73. This event is of the type defined in the requirements per 10CFR50.73 (a)(2)(iv). Also attached are the commitments made by the Authority in this LER.

Very truly yours,

John H. Garrity
Resident Manager
Indian Point Three Nuclear Power Plant

JHG/fp
Attachments

cc: Thomas T. Martin
Regional Administrator
Region 1
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406

INPO Records Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

180051

9306210393 930614
PDR ADDOCK 05000286
S PDR

JE22

ATTACHMENT
LIST OF COMMITMENTS MADE IN LETTER IPN-93-061

Number	Commitment	Due
IPN-93-061-01	The I&C department has instituted a preventive refurbishment program which will assure that all of the steam generator level controllers in use will be replaced or refurbished by June 1, 1994. This refurbishment program will also assure, by June 1, 1994, that level controllers in stores are ready for service.	June 1, 1994.