

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



John H. Garrity
Resident Manager

July 15, 1993
IPN-93-086

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station PI-137
Washington, D.C. 20555

SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Licensee Event Report LER 93-013-01
"Personnel Error, inattention to detail,
resulted in possible failure of Fan Cooler
Unit Dampers to operate"

Dear Sir:

The attached Licensee Event Report, LER 93-013-01, is hereby submitted in accordance with the requirements of 10CFR50.73. This LER revision was required to provide the complete safety significance of the event. This event is of the type defined in the requirements per 10CFR50.73 (a)(2)(i)(B). No new commitments are being made by this submittal.

Very truly yours,

A handwritten signature in cursive script that reads 'John H. Garrity'.

John H. Garrity
Resident Manager
Indian Point Three Nuclear Power Plant

JHG/vjm

cc: See Next Page

9307210020 930715
PDR ADOCK 05000286
S PDR



IE22
11

Mr. Thomas T. Martin
Regional Administrator
Region 1
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Records Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

U.S. NRC Resident Inspectors' Office
Indian Point Unit 3