OPERATING DATA REPORT

DOCKET NO. 50-286
DATE 12-1-80
COMPLETED BY C. Connel1
TELEPHONE 914 739-8200

| OPERATING | STATUS |
|------------------|--------|
|------------------|--------|

| 1. Unit Name: Indian Point No.3 Nuc | lear Power Plant | Notes | en e |
|--|-----------------------------|-------------------------|--|
| 2. Reporting Period: November 1980 | | | |
| | 3025 | | |
| · / | 1013 | | |
| , () · · · · · · · · · · · · · · · · · · | | | |
| 5. Design Electrical Rating (Net MWe): | 965). 952 | | |
| 6. Maximum Dependable Capacity (Gross MWe | 917 | | |
| 7. Maximum Dependable Capacity (Net MWe): | | | |
| 8. If Changes Occur in Capacity Ratings (Items | Number 3 Through 7) Sin | ce Last Report, Give Re | asons: |
| | | | |
| | -72 | | |
| 0.0 | | | |
| 9. Power Level To Which Restricted, If Any (No. | - /- | | |
| 10. Reasons For Restrictions, If Any: | V/A | | |
| | | | |
| | | | |
| | | • | anto de la arte a como Como de la como de la Como de la como de la c |
| | This Month | Yrto-Date | Cumulative |
| 11. Hours In Reporting Period | 720 | 8,040 | 37,297 |
| 12. Number Of Hours Reactor Was Critical | 0 | 4,856.3 | 26,441.1 |
| 13. Reactor Reserve Shutdown Hours | 0 | 0 | 0 |
| 14. Hours Generator On-Line | . 0 | : | |
| | 0 | 4,385.7 | 25,418.6 |
| 15. Unit Reserve Shutdown Hours | 0 | | 0 |
| 16. Gross Thermal Energy Generated (MWH) | | 10,800,817 | 66,905,284 |
| 17. Gross Electrical Energy Generated (MWH) | 0 | 3,017,310 | 21,382,411 |
| 18. Net Electrical Energy Generated (MWH) | 0 | 2,871,081· 54.5 | 20,514,518 |
| 19. Unit Service Factor | 0 | | 68.2 |
| 20. Unit Availability Factor | <u></u> | 54.5 | 68.2 |
| 21. Unit Capacity Factor (Using MDC Net) | 0 | 38.9 | 60.0 |
| 22. Unit Capacity Factor (Using DER Net) | 0 | 37.0 | 57.0 |
| 23. Unit Forced Outage Rate | | | 1.3 |
| 24. Shutdowns Scheduled Over Next 6 Months (1 | Type, Date, and Duration of | of Each): | S. D. B. S. C. |
| Continuing work on fire protect | ion modifications | and containment | fan |
| cooler unit repairs, anticipate | return to service | December 1980. | · · |
| If the Down At End Of Barrier | | Docombox 1990 | |
| 25. If Shut Down At End Of Report Period, Estin | • | December 1980. | |
| 26. Units In Test Status (Prior to Commercial Op | eration): | Forecast | Achieved |
| INITIAL CRITICALITY | | N/A | N/A |
| INITIAL ELECTRICITY | • | N/A | N/A |
| COMMERCIAL OPERATION |)N | N/A | N/A |
| OI ERATIC | ••• | | |

AVERAGE DAILY UNIT POWER LEVEL

| DOCKET NO. | Indian Point |
|--------------|-------------------|
| UNIT | Indian Point No.3 |
| DATE | 12-1-80 |
| COMPLETED BY | |
| TELEPHONE | 914-739-8200 |

| MONT | H November 1980 | | | t |
|----------|-------------------------------------|-----|-----|-------------------------------------|
| DAY | AVERAGE DAILY POWER LEVEL (MWe-Net) | | DAY | AVERAGE DAILY POWER LEVEL (MWe-Net) |
| 1 | 0 | | 17 | 0 |
| 2 . | 0 | | 18 | 0 |
| .3 | 0 | | 19 | <u> </u> |
| 4 | 0 | | 20 | 0 |
| 5 | 0 | • | 21 | 0 |
| 6 | 0 | - | 22 | <u> </u> |
| 7 | 0 | | 23 | 0 |
| 8 | <u> </u> | • | 24 | 0 |
| 9 | 0 | | 25 | 0 |
| 10 | 0 | | 26 | 0 |
| 11 | 0 | | 27 | 0 |
| 12 | 0 | - · | 28 | 0 |
| 13 | 0 | | 29 | 0 |
| 14 | | .* | 30 | 0 |
| 15 | 0 . | | 31 | _ |
| 16 | | • | J1 | |

INSTRUCTIONS

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

November 1980

Month

| | : | | Section 1995 Annual State of the Control of the Con | |
|----------|--------------|---------------------------------------|--|---------------------------------|
| | | | • | |
| Doto | 11 D # | | | |
| Date | W.R. # | Equipment | Malfunction | Corrective Action |
| | | | | |
| 10- 8-80 | 1C-1-1012-1C | #33 Static Inverter | No Output | Replaced blown fuse on Power |
| | | | . ` | Module #1. |
| | | | | |
| | -! | | | |
| 10-29-80 | 1C-1-953-3C | Static Inverters | None - preventive maint. | Replaced all precharge and |
| | | | | output capacitors in 31, 32, |
| | | · · · · · · · · · · · · · · · · · · · | | and 33 inverters. |
| | | · | . * | |
| | | | | |
| 10-29-80 | 1C-1-1019-3C | #32 Inverter | No Output | Replaced Diode D5 |
| | | } | | i i |
| | | | , | |
| 11-17-80 | 1C-1-741-2 | Chan 41 NIS ind. | Unable to set to specs. per | Repaired Cold Solder Connection |
| | | | Surveillance test 3PC-Ml | on Shunt resistor to meter. |
| | | | | |
| | | | | |
| | | | | , |
| | | | | • |
| | | | , | |
| | | | · | |
| | | | | |
| | · | | · | |
| | | | | |
| • | | | | |
| | | | | . ! |
| | | | | . 1 |
| | İ | | | |
| | | | | · |
| • | | · | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | : |
| | | , | - | |
| | 1 | 1 | - | • |

| November | 1980 |
|----------|------|
| November | TAOA |

Month

| | | | | Month |
|--------|----------------------|---------------------------|---------------------------------|------------------------------------|
| DATE: | W.R. # | EQUIPMENT | MALFUNCTION | CORRECTIVE ACTION |
| 2241-2 | II I 1156 | #33 Charging Pump | Leaking seals | Replaced packing |
| 11-9 | 1-0340 | #33 Atmos Steam Dump Vlv. | Excessive packing leak | Repacked Valve |
| 11-12 | I-0865 | MOV 535 | Valve will not operate | Adjusted limits |
| 11-13 | I-0909 | #31/32 RHR Pump | Inspection of rotor locknut | Inspection Satisfactory |
| 11-06 | I-0987 | MS-2-32 | Leaking Seals | Replaced packing |
| 11-05 | 1-0992 | #31 Atmos Relief Valve | Excessive packing leak | Repacked Valve |
| 11–13 | I - 1159 | LCV-459 Letdown Stop Vlv. | Dual Indication | Adjusted limits |
| 11-14 | I - 1185 | Valve 956 A,B,D,E,F | Improper indication | Adjusted limits |
| 11-12 | I-1330 | Valve 955A | Improper Operation | Adjusted limits |
| 11-06 | I - 1417 | Penetration H-13 | N/A | Installed original rebuilt |
| 11-04 | I - 1541 | Control Room A/C | Open limits | penetration Reset limits |
| 11-3 | I - 1555 | Valves SWNs 44, 41 | Valves Leak through | Replaced valve internals |
| 11-13 | I - 1567 | #31 Charging Pump | Broken "U" bolt | Replaced "U" bolt |
| 11-4 | I-1574 | #32 Atmos Steam Dump V1v | Excessive packing leak | Repacked valve |
| 11-5 | I - 1575 | #34 Atmos Steam Dump Vlv | Excessive packing leak | Repacked valve |
| 11-12 | I - 1579 | #33 Charging Pump | Breaker will not close properly | Adjusted closing spring |
| 11-8 | I - 1582 | VC Liner Insulation | Liner Insulation separation | Repositioned Insulation and sealed |
| | | | | |

| • | | | | Month |
|-------|-----------------|---------------------------------|---------------------------|---|
| DATE | W.R. # | EQUIPMENT | MALFUNCTION | CORRECTIVE ACTION |
| | | | | |
| 11-8 | I - 1585 | #31/32/34 Service Water Pump | Leaking Seals | Replaced packing |
| 11-14 | I - 1597 | #32 Fan Cooler Unit | "B" Damper will not close | Cleaned ram of debris |
| 11-14 | I - 1598 | Valve 955D | Air Diaphragm is damaged | Replaced Air regulator |
| 11-15 | I-1599 | #32 RHR Pump | Excessive Seal Leakage | Replaces seals |
| 11-12 | I-1600 | #31 Reactor Coolant Pump | Component Cooling leak | Repaired leak |
| 11-13 | I-1602 | #34 Reactor Coolant Pump | Component Cooling leak | Repaired leak |
| 11-14 | I-1604 | R-11/R-12 | Blower vanes are worn | Rebuilt Blower |
| 11-23 | I - 1642 | #31 Charging Pump | Excessive seal leakage | Replaced packing |
| 11-28 | I-1644 | #32 RHR Pump | Weld Leak | Replaced piping as necessary and welded |
| 11-25 | I -1 641 | #32 Fan Cooler Unit | Improper damper setting | Reset Damper |
| | | | · | |
| | | | | |
| | | | | |
| | | | | |

T 1

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH November 1980

DOCKET NO. <u>50-286</u> UNIT NAME Indian Pt. DATE 12-1-80 COMPLETED BY C. Connell (914) 739-8200 TELEPHONE

| Nu. | Date | Type1 | Duration (Hours) | Reason? | Method of Shutting Down Reactor3 | Licensce Event Report # | System Cude ⁴ | Component Code ⁵ | Cause & Corrective Action to Prevent Recurrence |
|----------|------------------|--------|---------------------|---------|----------------------------------|-------------------------------|-----------------------------|--------------------------------|--|
| 29 30 | 800930 801106 | S S | 168 432 | B B | 1 NA | NA NA | ZZ AB | ZZZZZ XXXXX | Turbine Outage (continued) Fire Protection Modifications |
| 31 | 801125 | S | 120 | В | NA | NA. | SB | HTEXCH ~ | Fan Cooler Unit, inspection, repair and testing. |

F: Forced S: Scheduled

Reason:

A-Equipment Failure (Explain)
B-Maintenance of Test

C-Refueling

D-Regulatory Restriction E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain) H-Other (Explain)

Method:

1-Manual

2-Manual Scram.

3-Automatic Scrain.

4-Other (Explain)

Exhibit F - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

Exhibid - Same Source

(9/77)

SUMMARY OF OPERATING EXPERIENCE November 1980

The Unit remained shutdown for the entire month of November. The turbine repairs were completed on November 6, 1980. The fire protection system modifications continued to be installed. Repairs were performed on various leaks on the cooling coils of the fan cooler units.