

John D. O'Toole  
Assistant Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-2533

January 28, 1981

Re: I.P. Units Nos. 2 and 3  
Docket Nos. 50-247 and  
50-286


Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Denton:

In accordance with Paragraph 2.E(4) of Facility Operating License No. DPR-26 and Paragraph 2.E(1) (f) of Facility Operating License No. DPR-64, enclosed herein is one copy of the Report entitled "Indian Point Generating Station Entrainment and Near Field River Studies 1977 Annual Report" dated December 1980. The Affidavit of Service of this report is enclosed.

By copy hereof this document is being filed with the Chief, Operating Reactors Branch No. 1, Division of Licensing, and with the Secretary of the Commission.

Very truly yours,



vdj

Enclosures:

cc: See page 2

A007  
s  
1/1

R 8102040442

cc: Samuel J. Chilk, Secretary (6 copies)  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Steven A. Varga, Chief (1 copy)  
Operating Reactors Branch 1  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

George T. Berry, President (1 copy)  
Power Authority of the State of  
New York  
10 Columbus Circle  
Room 1800  
New York, NY 10019