July 17, 1987 87-JK-040N

The following report is submitted as required under Part II, General Conditions, for SPDES permit NY0004472, reporting of non-compliance.

| | Outfall . | Parameter | Reported Maximum Value | Effluent Limit |
|----|-----------|-----------|------------------------|----------------|
| 1) | 001A | flow | 33, 800 gpd | 20, 000 gpd |

The additional flow (over 20,000 gpd) is due to an increased site population, relative to that upon which treatment plant design was based. Discussions of site population and its effect on treatment plant performance have previously been submitted to the D.E.C. Plans to resolve the site's daily flow requirements, are being actively pursued.

JK/pm



Consolidated Edison Company of New York, Inc. Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

July 17, 1987

Water Division
New York State Department of
Environmental Conservation
50 Wolf Road
Albany, New York 12233 •

Re: Monthly Discharge Monitoring Report
Permit Number 0004472
Con Edison Indian Point Units 1 and 2
New York Power Authority Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR's) for the month of June 1987.

Explanation for permit circulating flow deviations are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed. The site excursions are listed on Attachments to the cover letter.

If you have any questions regarding this submission, please contact Mr. Gerald Rumold of Con Edison at (914) 526-5681 or Mr. James Gillen of New York Power Authority at (914) 736-8450.

py truly yours,

John A. Basile, General Manager

Nuclear Power Generation

Con Edison, Indian Point 1 and 2

JJH: sh

Enclosure