

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: <i>Non destructive Testing 3035 W. Pasadena Ave Flint, MI</i>		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
REPORT NUMBER(S) 2009/001			

3. DOCKET NUMBER(S) <i>03035807</i>	4. LICENSEE NUMBER(S) <i>21-32340-01</i>	5. DATE(S) OF INSPECTION <i>Nov 18, 2009</i>
--	---	---

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	<i>G. Park</i>	<i>[Signature]</i>	<i>11/18/09</i>

[Handwritten mark]

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Non-Destructive Testing REPORT NUMBER(S) 2009-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 03035807	4. LICENSE NUMBER(S) 21-32340-01	5. DATE(S) OF INSPECTION 11/18/09	
6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS 3/01-07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3320	2. PRIORITY 1	3. LICENSEE CONTACT Patrick Durkin	4. TELEPHONE NUMBER (810) 424-2524
----------------------------	------------------	---------------------------------------	---------------------------------------

Main Office Inspection Next Inspection Date: 11/2010

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE
Program Scope
87121

The licensee is a radiographic inspection firm located in Flint, Michigan that performs work at auto assembly plants. The licensee has implemented the full increased control program and was performing work using an iridium-192 source. No changes in personnel have been made since the last increased controls inspection. All aspects of the increased controls program continues to be in place and performing adequately. Licensee has four card certified radiographers and five helpers for their work.

Performance Observations

The inspector toured the facility and checked radiation levels around the perimeter of the storage vault. Independent surveys performed by the inspector did not detect any unexpected reading. Interviews of licensee personnel indicated they had an adequate level of knowledge. Dosimetry readings indicate no exposures greater than 1 rem for the year. All radiographers were in possession of current ASNT certification cards or equivalent state cards. Licensee had in his possession records of the RSO audit of each radiographer and records of instrument calibration. No violations of requirements were identified.

Handwritten initials