



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
475 ALLENDALE ROAD  
KING OF PRUSSIA, PA 19406-1415**

December 18, 2009

Mr. John T. Carlin  
Site Vice President, R.E. Ginna Nuclear Power Plant  
R.E. Ginna Nuclear Power Plant, LLC  
1503 Lake Road  
Ontario, NY 14519

**SUBJECT: RESPONSE TO NOTICE OF VIOLATION EA-09-249 AND NRC INSPECTION  
REPORT 05000244/2009008**

Dear Mr. Carlin:

Thank you for your letter of December 9, 2009, in response to our November 12, 2009, letter and Notice of Violation concerning activities associated with a failure to preclude reoccurrence of a significant condition adverse to quality associated with the turbine driven auxiliary feedwater pump governor control valve, that led to a failure of the TDAFW pump to operate on July 2, 2009. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

Glenn T. Dentel, Chief  
Projects Branch 1  
Division of Reactor Projects

Docket No. 50-244  
License No. DPR-18

cc: Distribution via ListServ

December 18, 2009

Mr. John T. Carlin  
Site Vice President, R.E. Ginna Nuclear Power Plant  
R.E. Ginna Nuclear Power Plant, LLC  
1503 Lake Road  
Ontario, NY 14519

SUBJECT: RESPONSE TO NOTICE OF VIOLATION EA-09-249 AND NRC INSPECTION  
REPORT 05000244/2009008

Dear Mr. Carlin:

Thank you for your letter of December 9, 2009, in response to our November 12, 2009, letter and Notice of Violation concerning activities associated with a failure to preclude reoccurrence of a significant condition adverse to quality associated with the turbine driven auxiliary feedwater pump governor control valve, that led to a failure of the TDAFW pump to operate on July 2, 2009. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

/RA/

Glenn T. Dentel, Chief  
Projects Branch 1  
Division of Reactor Projects

Docket No. 50-244  
License No. DPR-18

cc: Distribution via ListServ

Distribution w/encl: (via E-mail)  
S. Collins, RA (R1ORAMAIL RESOURCE)  
M. Dapas, DRA (R1ORAMAIL RESOURCE)  
D. Lew, DRP (R1DRPMAIL RESOURCE)  
J. Clifford, DRP (R1DRPMAIL RESOURCE)  
L. Trocine, RI OEDO  
G. Dentel, DRP  
N. Perry, DRP

J. Hawkins, DRP  
S. Sloan, DRP  
K. Kolaczyk, DRP, SRI  
L. Casey, DRP, RI  
M. Rose, DRP, OA  
RidsNrrPMREGinna Resource  
RidsNrrDorILpl1-1 Resource  
[ROPreportsResource@nrc.gov](mailto:ROPreportsResource@nrc.gov)

SUNSI Review Complete: JRH (Reviewer's Initials)

DOCUMENT NAME: G:\DRP\BRANCH1\Ginna\Ginna NOV Response Ltr 2009008.doc ML 093520842

After declaring this document "An Official Agency Record" it will/will not be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRP	RI/DRP					
NAME	JHawkins/JRH	GDentel/GTD					
DATE	12/17/09	12/17/09					