

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

March 21, 1974

RE: Indian Point Unit No. 2
Facility Operating License
DPR-26

Mr. Eldon J. Brunner, Chief
Reactor Operations Branch
Regulatory Operations, Region I
U.S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Brunner:

Your letter of February 26, 1974 stated that certain activities authorized under A.E.C. License No. DPR-26 appeared to be in violation of A.E.C. requirements based on an inspection conducted by Mr. Anthony Fasano of your office on January 17-18, 21-22, 24-25 and 28, 1974. A description of these violations was provided as an enclosure to your letter. Pertinent information relating to these apparent violations is provided below and is presented in the order shown on the above referenced enclosure.

1. A separate response to this apparent violation was provided in a letter dated January 28, 1974 from Warren R. Cobean, Jr. to James P. O'Reilly.
2. The delay in reporting A.O. 4-2-1 was due to misinterpretation of the responsibility for processing such occurrences. Since that time Station Administrative Order (SAO) No. 124 has been issued to clarify the procedure to be followed by all Indian Point Units regarding the reporting of, and appropriate follow-up on, anomalous conditions, unexpected transients, equipment malfunctions, etc. This SAO clearly defines the required steps and responsibilities necessary to insure that the actions and notifications required by the Technical Specifications can be made within the specified time requirements.

8111070172 740405
PDR ADDCK 05000247
PDR

3. The monthly report to the Department Manager and each Section Head on the status of active Engineering Service Memorandums (ESM) and Engineering Service Requests (ESR) was not issued by the Station's Technical Engineering Director primarily because such a report would have only been redundant to a similar monthly status report which was being provided directly by our Engineering Department to key station personnel (such as, the Department and Station Managers, Director - Technical Engineering, Maintenance Superintendent, and the Chief Operations Engineer).

Station Administrative Order No. 109 has been revised to delete the requirement for the issuance of a periodic status report, and in lieu thereof, now requires that the Director - Technical Engineering maintain cognizance of the status of ESM's and ESR's for the purpose of being able to properly respond to specific requests for information.

Very truly yours,



William J. Cahill, Jr.