

Carl L. Newman
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N. Y. 10003
Telephone (212) 460-5133

REGULATORY DOCKET FILE COPY

October 28, 1976

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
ATTN: Mr. Robert W. Reid, Chief
Operating Reactors Branch # 4
Division of Reactor Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Gentlemen:

Herewith enclosed for your information are ten (10) additional copies of the following procedures for the Indian Point Unit No. 2 plant, which have previously been provided to members of your staff.

POP - 3.4 Rev 0 Low Pressure Operation without a steam Bubble


SOP - 1.3 Rev 0 Reactor Coolant Pump Operation

POP - 1.1 Rev 0 Plant Heatup from Cold Shutdown Condition

POP - 3.3 Rev 0 Plant Cooldown from zero power condition to cold shutdown condition

SOP - 1.1 Rev 0 Filling and Venting the Reactor Coolant System

SOP - 3.4 Rev 0 Collapsing the Steam Bubble in the Pressurizer.



PP/mmg



Very truly yours,

Carl L. Newman
Carl L. Newman
Vice President

Enclosures

11049

8111070571 761028
PDR ADOCK 05000247
P PDR