Vice President

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N Y 10003 Telephone (212) 460-3819

December 13, 1978

Re: Indian Point Unit No. 2 Docket No. 50-247 LER-78-032/03L-0

Mr. Boyce H. Grier, Director Office of Inspection and Enforcement Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Dear Mr. Grier:

The attached Licensee Event Report LER-78-032/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.d.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours,

REGULATORY DOCKET FILE COPY

William J. Cahill, Jr. Vice President

Attach.

CC: Mr. John G. Davis, Acting Director (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. T. Rebelowski, Resident Inspector U. S. Nuclear Regulatory Commission P. O. Nox 38 Buchanan, N. Y. 10511