


William J. Cahill, Jr.
Vice President

REGULATORY FILE COPY

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819



February 17, 1976

Re Indian Point Unit No. 2
Docket No. 50-247
R.O. -76-2-4(B)
R.O. -76-2-5(A)

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
King of Prussia, Penn. 19406



Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-26, the enclosed reports of Reportable Occurrences R.O. -76-2-4(B) and R.O. -76-2-5(A) are submitted. These reports fulfill the requirement for written reports within 30 days and 14 days of Reportable Occurrences and are in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachments are enclosed as required.

Very truly yours

William J. Cahill, Jr.
Vice President

enc.
mk

Copy to Director of Nuclear Reactor Regulation
Attn: Mr. Donald F. Knuth, Director (40 Copies)
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director of Nuclear Reactor Regulation
Attn: Mr. William F. McDonald, Director (3 Copies)
Office of Management Information and
Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

1703

8111090116 760217
PDR ADOCK 05000247
S PDR